

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.	30-025-33019
5. Indicate Type of Lease	STATE ☐ FEE ☒
6. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:	OIL WELL ☒ GAS WELL ☐ OTHER ☐
2. Name of Operator	AMERADA HESS CORPORATION ATTN: ONSHORE DRILLING SVS.
3. Address of Operator	P.O. BOX 2040 HOUSTON, TEXAS 77252
4. Well Location	Unit Letter <u>F</u> : <u>2650</u> Feet From The <u>NORTH</u> Line and <u>2630</u> Feet From The <u>WEST</u> Line

7. Lease Name or Unit Agreement Name	NORTH MONUMENT GRAYBURG
	SAN ANDRES UNIT
8. Well No.	284
9. Pool name or Wildcat	EUNICE MONUMENT G/SA

Section <u>4</u>	Township <u>20S</u>	Range <u>37E</u>	NMPM	LEA	County
10. Elevation (Show whether DF, RKB, RT, GR, etc.)					
GR. 3557					

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK ☐	REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐	ALTERING CASING ☐
PULL OR ALTER CASING ☐	COMMENCE DRILLING OPNS. ☐
OTHER: ☐	PLUG AND ABANDONMENT ☐
	CASING TEST AND CEMENT JOB ☒
	OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

7-19-95: DRILL TO 3,703'. RIG UP BULL ROGERS CSG. CREW. RUN 90 JTS. 7" 20# K55 8RS SMLS R3 "A". SET @ 3,703', SHOE @ 3,701', FLOAT @ 3,616', 12 TURBOLIZERS. CMT. W/HALLIBURTON. PUMP 600 SX. CLASS C + HALLILITE, + 5#/SX SALT + 1/4# SX. C.F. (12.6# 1.99) 300 SX. CLASS H + 5#/SX CAL-SEAL (16# 1.17) DISPL. W/146 BBLS BRINE WATER @ 6-4 BBLS/MIN. FINAL CIRC. W/1100 PSI. BUMP PLUG W/1600 PSI @ 1:30 P.M. GOOD RETURNS, CIRC. 143 SX. CMT. TO PIT. TEST TBG. HD. W/1100 PSI. O.K. TEST BLIND RAMS & CHOKE MANIFOLD W/1500 PSI. O.K.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Mike Jumper TITLE ADM. SUPVSR. DRILG. SVS. DATE 07-20-95
(713)
TYPE OR PRINT NAME MIKE JUMPER TELEPHONE NO. 609-4846

(This space for State Use)

Checked by
Paul Jantz
Geologist

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY:

AUG 07 1995

7-16-1995

JUL 24 1995

OLD HOBBS
OFFICE

JUL 24 1995

C