Form 3160-5 (June 1990)

1. Type of Well X Oil Well

2. Name of Operator

3. Address and Telephone No.

UNITED STATES DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT**

N.M Oil Cons P.C. LX 1980 Hobbs, NM 88241

FORM APPROVED Budget Bureau No. 1004-0135

Expires: March 31, 1993 5. Lease Designation and Serial No.

6. If Indian, Allottee or Tribe Name

LC-065607

30-025-33181 10. Field and Pool, or Exploratory Area

NE Lea Delaware 11. County or Parish, State

SUNDRY	NOTICES	AND RE	PORTS (ON MEL	LS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir. Use "APPLICATION FOR PERMIT-" for such proposals

SUBMIT IN TRIPLICATE

3 12 1123	
7. II Unit	or CA, Agreement Designation
8. Well Nar	ne and No.
Huds	on Federal #4
9. API Wel	No.

P. O. Box 1518 Roswell, New Mexico 88202-1518
4. Location of Well (Foolage, Sec., T., R., M., or Survey Description)

Other

1650' FNL & 2310' FWL

Gas Well

Read & Stevens, Inc.

Se	ection 4 T2OS-R34E		Lea County, New Mexico	
2.	CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPO	RT, OR OTHER DATA	
	TYPE OF SUBMISSION	TYPE OF ACTION		
	Notice of Intent Subsequent Report Final Abandonment Notice	Abandonment Recompletion Plugging Back Casing Repair Altering Casing	Change of Plans New Construction Non-Routine Fracturing Water Shut-Off Conversion to Injection	
		X Other <u>Acidize/Frac Perfs</u>	Dispose Water (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log (orm.)	

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

10/20/97 MIRUSU. Set CIBP @ 8,025'. Dump bail 2 sx cmt. Set CIBP @ 7,225' and dump bail 2 sx cmt on top. Perf 4 SPF in Delaware @ 5,600'-20'. Total 80 holes.

10/21/97 Acidize well by pumping 1,000 gal 7 1/2% NEFe HCl via tbg. Spaced 120 7/8" OD BS's. Flush w/ 35 bbls 2% KCl wtr. Balled out to 5,200 psi w/ 108 BS's on formation. Surge balls & complete job pumping add 1 bbl of flush wtr. RD acid crew. Swab well to SN recovering 36 BLW. No oil cut.

10/22/97 Pull swab from 4,200' recovering 100% wtr. Rls pkr. POH w/ tbg laying down pkr. Close BOP. Prep to fracture stimulate this AM.

10/23/97 RU frac crew. Fracture stimulate well w/ 50,000# 16/30 Ottawa sand and contained in 30# x-linked gel.

10/24/97 NDBOP. Set TAC @ 5,522' w/ 10,000# tension. SN @ 5,616'. EOT @ 5,649'. NUWH. Seated and spaced pump. Hung on w/ excellent pump action. Left well pumping to battery on 144" stroke w/ 8 SPM, RDMOSU,

14. I hereby cereify that the forceoing is true and correct Signed	Title	-Petroleum Engineer	Date 1-9-98				
(This space to Federal or Late office use) Approved by Conditions of approval, if any:	Title	ACCEPTED FOR RECORD ORIG. SGD. DAVID R. GLASS JAN 1 2 1898	Date				
Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and will fully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.							