Submit 3 Copies to Appropriate District Office

CONDITIONS OF APPROVAL, IF ANY:

State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 1-1-89

District Office			
DISTRICT I	L CONSERVATIO		WELL API NO.
P.O. Box 1980, Hobbs NM 88241-1980 P.O. Box 2088 DISTRICT II Santa Fe New Mexico 87504-2088			30-025-33190
DISTRICT II P.O. Drawer DD, Artesia, NM 88210 Santa Fe, New Mexico 87504-2088			5. Indicate Type of Lease
DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410			STATE FEE X 6. State Oil & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS			
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)			7. Lease Name or Unit Agreement Name
1. Type of Well:	POR SUCH PROPOSALS.)		N F Outles
OIL GAS WELL WELL	OTHER		M. E. Gaither
2. Name of Operator			8. Well No.
Amerada Hess Corporation 3. Address of Operator	*		5 0 Polosos Wildon
P. O. Drawer D, Monument, NM 88265			9. Pool name or Wildcat MONUMENT ABO
4. Well Location Unit Letter I : 1650 F	Feet From The South	Line and 66	0 Feet From The East Line
Section 34	Township 19S Rar	nge 36E	NMPM Lea County
	10. Elevation (Show whethe	r DF, RKB, RT, GR, etc	
11. Check Approx	WA Pay to Indicate I	3621' GR	Parada Od Parada
The Parameter of Marie Water of Marie, Report, of Other Parameter of Marie Water of Marie Parameter of Marie			
NOTICE OF INTE	MITONIO:	308	SEQUENT REPORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLING	OPNS. PLUG AND ABANDONMENT
PULL OR ALTER CASING		CASING TEST AND CEI	
OTHER:		OTHER: New We	Il Completion.
12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. 1-8 thru 2-5-96 MIRU Pride Well Svc. pulling unit & installed BOP. TIH w/4-3/4" bit & 5-1/2" csg. scrappers to 7990' & TOH. Schlumberger ran CBT cement bond log. TIH & tagged bottom at 7997'. Logged up to 6000' & found top of cement at 6942'. Re-logged across top of cement w/500 & 1000 PSI. No change in cement top. TIH w/Hyper Jet III charges & perforated ABO Zone 5-1/2" csg. w/2 SPF, total 208 shots at following intervals: 7551' - 7583'. 7588' - 7603', 7612' - 7617', 7622' - 7625', 7641' - 7648', 7707' - 7711', 7731' - 7740', 7745' - 7746', 7754' - 7759', 7763' - 7766', 7772' - 7774', 7776' - 7777', 7781' - 7782', & fr. 7792' - 7794'. TIH w/Halliburton 5-1/2" x 2-7/8" PPI pkr. Set pkr. at 7495' & tested w/3500 PSI. Held OK. Released pkr. & re-set at 7989'. Knox Svc. acidized Abo Zone 5-1/2" csg. perfs. fr. 7551' - 7794' w/5200 gal. 15% HCL acid. TOH w/pkr. Swabbed well. Recovered water, no oil w/slight blow of gas. Swab line parted. TOH recovering swab line. CONTINUED ATTACHED.			
SIGNATURE Senior Production Foreman DATE 2-21-96			
TYPE OR PRINT NAME ROBert L. Will	iams, Jr.		TELEPHONE NO. 505 393-2144
(This space for State Use) ORIGINAL SIGNED BY JERF	ty sexton		EED O A
DISTRICT I SUPERVI	SOR TITLE	E	FEB 26 1996