

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs NM 88241-1980

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.	30-025-33571
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.	
7. Lease Name or Unit Agreement Name	
J. W. SMITH	
8. Well No.	11
9. Pool name or Wildcat	MONUMENT; ABO
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	
3666'	

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
OIL WELL ☐ GAS WELL ☐ OTHER DRY

2. Name of Operator
Chevron U.S.A. Inc.

3. Address of Operator
P.O. Box 1150, Midland, TX 79702

4. Well Location
Unit Letter B : 720 Feet From The NORTH Line and 1650 Feet From The EAST Line
Section 34 Township 19S Range 36E NMPM LEA County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)
3666'

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: COMPLETED & SHUT IN <input checked="" type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

LOGGED. PERFD 7800'-7810' W/2 JHPF. ACZD PERFS W/750 GALS 15% NEFE. SET CIBP @ 7780'.
PERFD 7612'-7745' W/2 JHPF. ACZD W/550 GALS 7-1/2% NEFE. SET CIBP @ 7575'. PERFD
6868'-6921' W/1 JHPF. ACZD W/2100 GALS 15% NEFE, 46 RCNB'S. PERFD 6700'-6708' W/2 JHPF.
ACZD W/2100 GALS 15% NEFE; FRACD W/8000 GALS GEL, 16,500# SAND. TAGGED SAND @ 6679', CLEANED
OUT TO 6784'. DUMP 20' CMT ON CIBP @ 7575'. SET CIBP @ 6800'. RIH W/TBG. SET @ 6768'.

WELL SHUT IN.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE J. K. Ripley TITLE TECHNICAL ASSISTANT DATE 4/23/97

TYPE OR PRINT NAME J. K. RIPLEY TELEPHONE NO. (915)687-7148

(This space for State Use)

ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT I SUPERVISOR

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: