Submit 3 Copies to Appropriate

State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 1-1-89

District Office					
DISTRICT I P.O. Box 1980, Hobbs NM 88241-1980 OIL CONSERVATION DIVISION P.O. Box 2089			WELL API NO.		
P.O. Box 1980, Hobbs NM 88241-1980 P.O. Box 2088 DISTRICT II Santa Fe, New Mexico 87504-2088			30-025-33943		
P.O. Drawer DD, Artesia, NM 88210			5. Indicate Type	of Lease	FEE X
DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410			6. State Oil & G		FEE LAJ
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)					
			7. Lease Name or Unit Agreement Name NORTH MONUMENT G/SA UNIT		
1. Type of Well: OIL GAS WELL WELL OTHER	GAS C			2 4, 5, 1, 5, 11, 1	
2. Name of Operator			8. Well No.		
Amerada Hess Corporation			629		
3. Address of Operator P. O. Box 840. Seminole, Texas 79360-0840 4. Well Location			9. Pool name or Wildcat EUNICE-MONUMENT/GRAYBURG SAN ANDRES		
Unit Letter M : 530 Feet From The SC	DUTH	Line and 73	Feet Fro	om The WE	ST Line
Section 20 Township 19S		nge 37E	NMPM	LEA	County
10. Elevation (Show	w whethe	r DF, RKB, RT, GR, etc 3623' GR	e.)		
11. Check Appropriate Box to Ind	icata	·- · · · · · · · · · · · · · · · ·	Donout on	Other Date	
Check rippi opriate box to indicate return of recite			SSEQUENT REPORT OF:		
PERFORM REMEDIAL WORK PLUG AND ABANDON		REMEDIAL WORK		ALTERING CAS	SING
TEMPORARILY ABANDON CHANGE PLANS		COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT			
PULL OR ALTER CASING					
OTHER:		OTHER: NEW WI	ELL COMPLETIC	IN	[X
12. Describe Proposed or Completed Operations (Clearly state all perting)	nent deta	ils, and give pertinent da	tes, including estin	nated date of starti	ing any proposed
work) SEE RULE 1103.		,		UFX-	
11-02-1997 THRU 12-04-1997 ORDER NO. R9596					() (
TIH W/6-1/8" BIT. TAG FLOAT COLLAR @3822' &	DRILL	OUT FC & CMT TO	3913'. CIRC.	CSG CLEAN	
W/150 BFW. TEST CSG TO 2000 PSI. OK. RAN CBL/CCL/	GR LOG	S FROM 3901' - 29	013'. TIH W/4	" HEGS CASING	ì
GUNS & PERF. GRAYBURG/SAN ANDRES ZONE, 7" CS 3802'-					
3861', 3774'-3790', 3766'-3771' & 3746'-3757					
HAMMER, TAG TD @3913'. MIRU FRACMASTER ACIDI					
15% HCL 0.6% FERCHECK SC ACID. SWABBED WELL. TOH LAYING DWN FTI SONIC HAMMER. PICKED UP OFF RACKS & TIH TESTING TESTING TO 3000 PSI ABOVE THE SLIPS W/7" 1XS ARROWSET PKR W/ ON/OFF TOOL,					
117 JTS 2-3/8" POLYLINED TBG, & BREECH LOC MANDREL. SET PKR @3703' W/11000 #'S OF TENSION.					
CIRC W/150 BBLS OF PKR FLUID. REMOVED 6" 90					
NIPPLE UP WELLHEAD & TEST TO 3000 PSI. RD & I hereby No JETT THING WELLHEAD WE TEST TO 3000 PSI. RD &					
$\mathcal{L}_{\mathcal{L}}}}}}}}}}$		E STAFF ASSISTANT			
TYPE OR PRINT NAME COLLEEN ROBINSON	- ''''			TELEPHONE NO. 9	-
(This space for State Use) OBIGINAL SIGNED BY CHBIS WILL!	AMS			- 222.110.12.110.	13 /30 0//0
DISTRICT I SUPERVISOR					
APPROVED BY CONDITIONS OF APPROVAL, IF ANY:	тпт	E		DATE	
COMPLETIONS OF ALTROYALS IF A.T.					