

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

P.O. Box Drawer DD, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088

Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-34011
5. Indicate Type of Lease STATE ☒ FEE ☐
6. State Oil / Gas Lease No.
7. Lease Name or Unit Agreement Name NEW MEXICO 'E' STATE NCT-2
8. Well No. 2
9. Pool Name or Wildcat MONUMENT ABO
10. Elevation (Show whether DF, RKB, RT,GR, etc.) 3727'

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMI
(FORM C-101) FOR SUCH PROPOSALS.

1. Type of Well: OIL WELL ☒ GAS WELL ☐ OTHER ☐
2. Name of Operator
TEXACO EXPLORATION & PRODUCTION INC.
3. Address of Operator
205 E. Bender, HOBBS, NM 88240
4. Well Location
Unit Letter F : 2310 Feet From The NORTH Line and 2175 Feet From The WEST Line
Section 23 Township 19-S Range 36-E NMPM LEA COUNTY

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPERATION ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: ☐ HORIZONTAL DRILLING ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

4-15-00/4-25-00: MIRUSU. LD RD STRING. RU BOP. POH W/TBG. TIH W/BIT & CSG SCRAPER TO TOP OF PERFS @ 7595. WRK CSG SCRAPER FR 7150-7250. RU WL. TIH W/JNK BSKT & GAUGE RING. TIH W/WL SET TBG RETR & SET RBP @ 7190. TIH W/DMP BAILER & DUMP 1/2 SX OF SD ON TOP OF RBP. TIH W/TBG TO 7085 OPEN ENDED W/TBG. REV CIRC FW DN HLE TO CIRC OUT OIL & FLUID FR WELL. RD PUMP UNIT. MIRU KEY RIG #119. PU MILLS. TAG TOP OF SD @ 7182'. TIH W/WHIPSTOCK & DP. TIH W/GYRO TOOL. SET WHIPSTOCK W/198 DEG AZIMUTH. MILL W/STARTER MILL FR 7174-7175. WINDOW WILL BE FR 7174-7180 WHEN CUT. MILL FR 7175-80. PU DIREC TOOL & TIH. SLIDE DRILL 7183-7211, 7262,7315,7322,7342,7490,7542,7584,7595,7612,7616,7774,7781,7805,7812,7899,7914,7962,7967,8033. TD 4 3/4" HLE @ 23:30 MST 4-21-00. PUMP TDT LOG DN DP. STUCK LOGGING TOOL ON BTM. WRK FREE. LOG TDT LOG. PU WHIPSTOCK HOOK & TIH. JAR ON WHIPSTOCK UNTIL FREE. TIH W/RBP & SET @ 7010'. NDBOP. NDFL. REL RIG @ 1400 HRS 4-23-00.

MIRU COMPL UNIT. 4-25-00. PU RETR TOOL. TIH W/JET SUBS. PKR SET @ 6991. SN @ 6990'. INST FRAC TREE. LOADED TBG W/8 BFW. STARTED ACID 13 BPM 4800 PSI. ACID TO PERFS 20 BPM 3700 PSI. FINAL TREATING PRESS 20 BPM 2939. FLUSH W/84 BBLS FW. OPEN BYPASS ON PKR LET TBG & CSG EQUALIZE. PUMP 25 BFW DN TBG. PU PKR W/SN ON TOP OF PKR. TIH W/PROD TBG. PSA 7019. SN @ 7013 ON 2 7/8" TBG. FLANGE UP WH. KILL W/25 BFW. NUBOP. UNSEAT PKR PMP 25 BFW DN CSG. TIH ON 202 JTS 2 7/8" TBG TO 7025. LATCH ONTO RBP & WRK LOOSE. TIH W/RBP TO 7326. TIH W/PROD TBG, TBG ANCHOR, SN @ 7583. NDBOP. SET TA W/20,000 PULL OVER STRING WT. FLANGE UP TREE. TIH W/PMP & RDS. RIG DOWN 5-13-00.

5-21-00: ON 24 HR OPT. PUMPING 275 BO, 174 BW, & 204 MCF. FINAL REPORT

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE J. Denise Leake TITLE Engineering Assistant

DATE 7/18/00

TYPE OR PRINT NAME J. Denise Leake

Telephone No. 397-0405

(This space for State Use)

APPROVED

CONDITIONS OF APPROVAL IF ANY

TITLE

ORIGINAL SIGNED BY
PAUL F. KAUTZ
PETROLEUM ENGINEER

DATE

AUG 16 2002

DeSoto-Nichols 12-93 ver 1.0