Submit 3 Copies to Appropriate District Office

CONDITIONS OF APPROVAL, IF ANY:

Same of New Mexico Energy, Minerals and Natural Resources Department

Form C-	103
Revised	1-1-89

			ATION DIVISION	NACUL ADIAIO
P.O. Box 1980, Hobbs, NM 88240		2040 Pachec	o St.	WELL API NO. 30-025-34248
DISTRICT II		Santa Fe, N	M 87505	
P.O. Drawer DD, Artesia, NM 882	10			sindicate Type of Lease STATE X FEE FEE
DISTRICT III				sState Oil & Gas Lease No.
1000 Rio Brazos Rd., Aztec, NM 8	37410			E I 5 8 7
SIIND	RY NOTICES A	ND REPORTS ON	WELLS	
(DO NOT USE THIS FORM	FOR PROPOSAL	S TO DRILL OR TO DE	EPEN OR PLUG BACK TO A	rLease Name or Unit Agreement Name
DIFFEREN	NT RESERVOIR. 1	USE "APPLICATION FO OR SUCH PROPOSALS	R PERMIT"	
Type of Well:	(, 5,1,1, 5 15,) T		·	Lea AQ State
ا منذ ہے ج	as Fell	OTHER		
2Name of Operator	Operating	Company		sWell No.
Address of Operator	operating	Общрану		Pool name or Wildcat
	dow Rd.,	158, Dallas	TX 75231	Pearl San Andres, West
4Well Location				Woot
Unit Letter	940 Feet Fro	om The north	Line and1034	Feet From The West Line
Section 33	To	wnship 195	Range 35E	NMPM Lea County
		₁₀Elevation (Show wheth	ner DF, RKB, RT, GR, etc.	
California transmita kiser in a med istella	<u>addining and Alberta</u>	3709'		
11 C	heck Appropr	iate Box to Indica	te Nature of Notice, Re	
NOTICE	OF INTENT	TON TO:	SUB	SEQUENT REPORT OF:
PERFORM REMEDIAL WORK	[F	PLUG AND ABANDON	REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON		CHANGE PLANS	COMMENCE DRILLING	OPNS. X PLUG AND ANBANDONMENT
			CASING TEST AND SEN	MENT IOR
PULL OR ALTER CASING			CASING TEST AND CEN	MENT JOB X
				IENI JOB X
OTHER:			OTHER:	
OTHER:	ed Operations (Clear)	y state all pertinent details, a	OTHER:	estimated date of starting any proposed
OTHER: 12Describe Proposed or Complete work) SEE RULE 1103. Spudded ll" h	ole 1-25-	98. Drill t	other:ond give pertinent dates, including e	jts 8-5/8" 24# J55 STC
OTHER: 12Describe Proposed or Complete work) SEE RULE 1103. Spudded 11" h csg. Tally	ole 1-25-9	98. Drill t t @ 465'. B	oTHER: and give pertinent dates, including e o 455'. Ran 10 J cemented w/ 20	istimated date of starting any proposed jts 8-5/8" 24# J55 STC 00 sx C w/ 2% CaCl2 &
other: 12Describe Proposed or Complete work) SEE RULE 1103. Spudded 11" h csg. Tally 1/4 PPS Cel	ole 1-25-9 450', se loflake @	98. Drill t t @ 465'. B 14.8 PPG w/	oTHER:ond give pertinent dates, including end of 455 . Ran 10 J cemented w/ 20 1.32 CFS yld.	jts 8-5/8" 24# J55 STC 00 sx C w/ 2% CaCl2 & Bump plug OK, but float
other: Describe Proposed or Complete work) SEE RULE 1103. Spudded ll" h csg. Tally l/4 PPS Cel did not hol	ole 1-25-9 450', se loflake @ d. SI @	98. Drill t t @ 465'. B 14.8 PPG w/ surface. Ci	other: odgive pertinent dates, including e o 465'. Ran 10 J cemented w/ 20 1.32 CFS yld. rc 42 sx to pit	istimated date of starting any proposed jts 8-5/8" 24# J55 STC 00 sx C w/ 2% CaCl2 & Bump plug OK, but float . Screw on 8-5/8" Larkin
other: Describe Proposed or Complete work) SEE RULE 1103. Spudded ll" h csg. Tally l/4 PPS Cel did not hol fig 92 csg	ole 1-25-9 450', seg loflake @ d. SI @ s	98. Drill t t @ 465'. B 14.8 PPG w/ surface. Ci double ram	other: ond give pertinent dates, including end give pertinent dates, including end of 465'. Ran 10 Journal of the company of	istimated date of starting any proposed jts 8-5/8" 24# J55 STC 00 sx C w/ 2% CaC12 & Bump plug OK, but float . Screw on 8-5/8" Larkin ams on top. NU 3M ck
OTHER: 12Describe Proposed or Complete work) SEE RULE 1103. Spudded 11" h csg. Tally 1/4 PPS Cel did not hol fig 92 csg manifold.	ole 1-25-9 450', ser loflake @ d. SI @ : head. NU Test bline	98. Drill t t @ 465'. B 14.8 PPG w/ surface. Ci double ram d rams & man	other: ond give pertinent dates, including end give pertinent dates, including end of 465'. Ran 10 Journal of the company of	istimated date of starting any proposed jts 8-5/8" 24# J55 STC 00 sx C w/ 2% CaCl2 & Bump plug OK, but float . Screw on 8-5/8" Larkin
OTHER: 12Describe Proposed or Complete work) SEE RULE 1103. Spudded 11" h csg. Tally 1/4 PPS Cel did not hol fig 92 csg manifold.	ole 1-25-9 450', ser loflake @ d. SI @ : head. NU Test bline	98. Drill t t @ 465'. B 14.8 PPG w/ surface. Ci double ram	other: ond give pertinent dates, including end give pertinent dates, including end of 465'. Ran 10 Journal of the company of	istimated date of starting any proposed jts 8-5/8" 24# J55 STC 00 sx C w/ 2% CaC12 & Bump plug OK, but float . Screw on 8-5/8" Larkin ams on top. NU 3M ck
OTHER: 12Describe Proposed or Complete work) SEE RULE 1103. Spudded 11" h csg. Tally 1/4 PPS Cel did not hol fig 92 csg manifold.	ole 1-25-9 450', ser loflake @ d. SI @ : head. NU Test bline	98. Drill t t @ 465'. B 14.8 PPG w/ surface. Ci double ram d rams & man	other: ond give pertinent dates, including end give pertinent dates, including end of 465'. Ran 10 Journal of the company of	istimated date of starting any proposed jts 8-5/8" 24# J55 STC 00 sx C w/ 2% CaC12 & Bump plug OK, but float . Screw on 8-5/8" Larkin ams on top. NU 3M ck
OTHER: 12Describe Proposed or Complete work) SEE RULE 1103. Spudded 11" h csg. Tally 1/4 PPS Cel did not hol fig 92 csg manifold.	ole 1-25-9 450', ser loflake @ d. SI @ : head. NU Test bline	98. Drill t t @ 465'. B 14.8 PPG w/ surface. Ci double ram d rams & man	other: ond give pertinent dates, including end give pertinent dates, including end of 465'. Ran 10 Journal of the content of	istimated date of starting any proposed jts 8-5/8" 24# J55 STC 00 sx C w/ 2% CaC12 & Bump plug OK, but float . Screw on 8-5/8" Larkin ams on top. NU 3M ck
OTHER: 12Describe Proposed or Complete work) SEE RULE 1103. Spudded 11" h csg. Tally 1/4 PPS Cel did not hol fig 92 csg manifold.	ole 1-25-9 450', ser loflake @ d. SI @ : head. NU Test bline	98. Drill t t @ 465'. B 14.8 PPG w/ surface. Ci double ram d rams & man	other: ond give pertinent dates, including end give pertinent dates, including end of 465'. Ran 10 Journal of the content of	istimated date of starting any proposed jts 8-5/8" 24# J55 STC 00 sx C w/ 2% CaC12 & Bump plug OK, but float . Screw on 8-5/8" Larkin ams on top. NU 3M ck
OTHER: 12Describe Proposed or Complete work) SEE RULE 1103. Spudded 11" h csg. Tally 1/4 PPS Cel did not hol fig 92 csg manifold.	ole 1-25-9 450', ser loflake @ d. SI @ : head. NU Test bline	98. Drill t t @ 465'. B 14.8 PPG w/ surface. Ci double ram d rams & man	other: ond give pertinent dates, including end give pertinent dates, including end of 465'. Ran 10 Journal of the content of	istimated date of starting any proposed jts 8-5/8" 24# J55 STC 00 sx C w/ 2% CaC12 & Bump plug OK, but float . Screw on 8-5/8" Larkin ams on top. NU 3M ck
OTHER: 12Describe Proposed or Complete work) SEE RULE 1103. Spudded 11" h csg. Tally 1/4 PPS Cel did not hol fig 92 csg manifold.	ole 1-25-9 450', ser loflake @ d. SI @ : head. NU Test bline	98. Drill t t @ 465'. B 14.8 PPG w/ surface. Ci double ram d rams & man	other: ond give pertinent dates, including end give pertinent dates, including end of 465'. Ran 10 Journal of the content of	istimated date of starting any proposed jts 8-5/8" 24# J55 STC 00 sx C w/ 2% CaC12 & Bump plug OK, but float . Screw on 8-5/8" Larkin ams on top. NU 3M ck
OTHER: 12Describe Proposed or Complete work) SEE RULE 1103. Spudded ll" h csg. Tally l/4 PPS Cel did not hol fig 92 csg manifold. test pipe r	ole 1-25-9 450', set loflake @ d. SI @ s head. NU Test blind ams & TIW	98. Drill t t @ 465'. B 14.8 PPG w/ surface. Ci double ram d rams & man to 900 psi.	other: ond give pertinent dates, including end give pertinent dates, including end of 465'. Ran 10 Journal of the control of	its 8-5/8" 24# J55 STC OO sx C w/ 2% CaC12 & Bump plug OK, but float . Screw on 8-5/8" Larkin ams on top. NU 3M ck i. TIH w/ 7-7/8" BHA &
OTHER: 12Describe Proposed or Complete work) SEE RULE 1103. Spudded 11" h csg. Tally 1/4 PPS Cel did not hol fig 92 csg manifold. test pipe r	ole 1-25-9 450', set loflake @ d. SI @ s head. NU Test blind ams & TIW	98. Drill t t @ 465'. B 14.8 PPG w/ surface. Ci double ram d rams & man to 900 psi.	oTHER: and give pertinent dates, including et o 455'. Ran 10 J cemented w/ 20 1.32 CFS yld. rc 42 sx to pit BOP with pipe raifold to 900 ps	its 8-5/8" 24# J55 STC OO sx C w/ 2% CaC12 & Bump plug OK, but float . Screw on 8-5/8" Larkin ams on top. NU 3M ck i. TIH w/ 7-7/8" BHA &
OTHER: 12Describe Proposed or Complete work) SEE RULE 1103. Spudded ll" h csg. Tally l/4 PPS Cel did not hol fig 92 csg manifold. test pipe r	ole 1-25-9 450', set loflake @ d. SI @ s head. NU Test blind ams & TIW	98. Drill t t @ 465'. B 14.8 PPG w/ surface. Ci double ram d rams & man to 900 psi.	other: ond give pertinent dates, including end give pertinent dates, including end of 465'. Ran 10 Journal of the control of	its 8-5/8" 24# J55 STC Oo sx C w/ 2% CaC12 & Bump plug OK, but float Screw on 8-5/8" Larkin ams on top. NU 3M ck i. TIH w/ 7-7/8" BHA &
OTHER: 12Describe Proposed or Complete work) SEE RULE 1103. Spudded 11" h csg. Tally 1/4 PPS Cel did not hol fig 92 csg manifold. test pipe r	ole 1-25-9 450', set loflake @ d. SI @ s head. NU Test blind ams & TIW	98. Drill t t @ 465'. B 14.8 PPG w/ surface. Ci double ram d rams & man to 900 psi.	oTHER: and give pertinent dates, including et o 455'. Ran 10 J cemented w/ 20 1.32 CFS yld. rc 42 sx to pit BOP with pipe raifold to 900 ps	its 8-5/8" 24# J55 STC OO sx C w/ 2% CaC12 & Bump plug OK, but float . Screw on 8-5/8" Larkin ams on top. NU 3M ck i. TIH w/ 7-7/8" BHA &
OTHER: 12Describe Proposed or Complete work) SEE RULE 1103. Spudded 11" h csg. Tally 1/4 PPS Cel did not hol fig 92 csg manifold. test pipe r	ole 1-25-9 450', second of lake @ d. SI @ head. NU Test blind ams & TIW	98. Drill t t @ 465'. B 14.8 PPG w/ surface. Ci double ram d rams & man to 900 psi.	oTHER: and give pertinent dates, including et o 455'. Ran 10 J cemented w/ 20 1.32 CFS yld. rc 42 sx to pit BOP with pipe raifold to 900 ps	its 8-5/8" 24# J55 STC OO sx C w/ 2% CaC12 & Bump plug OK, but float Screw on 8-5/8" Larkin ams on top. NU 3M ck i. TIH w/ 7-7/8" BHA & Manager DATE /-28-97 214-987-7144 TELEPHONE NO.
OTHER: 12Describe Proposed or Complete work) SEE RULE 1103. Spudded 11" h csg. Tally 1/4 PPS Cel did not hol fig 92 csg manifold. test pipe r	ole 1-25-9 450', set loflake @ d. SI @ head. NU Test bline ams & TIW	98. Drill t t @ 465'. B 14.8 PPG w/ surface. Ci double ram d rams & man to 900 psi.	oTHER: and give pertinent dates, including et o 455'. Ran 10 J cemented w/ 20 1.32 CFS yld. rc 42 sx to pit BOP with pipe raifold to 900 ps	its 8-5/8" 24# J55 STC 00 sx C w/ 2% CaC12 & Bump plug OK, but float Screw on 8-5/8" Larkin ams on top. NU 3M ck i. TIH w/ 7-7/8" BHA &