Fc m 3160-5 (August 1999) Department of the Interior Diss, NM 38240 OMB No. 1004-0135 Expires November 30, 2000					
	- main state - p				
Department of the interior					
Bureau Of Land Management 5. Lease Serial No.					
Sundry Notices And Reports on Wells					
Do not use this form for proposals to drill or to re-enter an 6. If Indian, Allottee or Tribe Name	6. If Indian, Allottee or Tribe Name				
Abandoned well. Use form 3160-3 (APD) for such proposals.					
7. If Unit or CA/Agreement, Name and	7. If Unit or CA/Agreement, Name and/or No.				
SUBMIT IN TRIPLICATE – Other Instructions On reverse side 8. Well Name and No.	8. Well Name and No.				
1. Type of Well:					
	Neuhaus 14 Federal #3				
	9. API Well No.				
	30-025-35153				
J. Hadroos of optimite	10. Field and Pool, or Exploratory Area				
110 W Bouisiana, Sto 110 Milanana, 2000 1910	E. Featherstone Bone Spring				
4. Location of Well (Footage, Sec., T., R., M., or Survey Description) 11. County or Parish, State	11. County or Parish, State				
Les Counter Menine	Les Countre Nous Mouris-				
Unit 0, 000 FSL & 1980 FEL, Sec 14, 1203, RS5E	Lea County, New Mexico				
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data					
Type Of Submission Type Of Action	Type Of Action				
Acidize Deepen Production (Start/Resume) Water Shut-Of					
🕅 Notice of Intent					
Subsequent Report  Casing Repair  New Construction  Recomplete  Other					
	•				
Convert to Injection Plug Back Uwater Disposal					

13. Describe proposed or completed operations. (clearly state all pertinent details, starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

- MIRU. PU tbg to plug. RIH openended to 9700'. Plug #1 spot 25 sxs f/ 9700' 9600', PUH to 6700', plug #2 spot 25 sxs f/ 6700' 6000'. POH 1550'
  2. U for 5-1/2" csg @ 4100'. RIH openended to 4100', plug #3 spot 35 sxs f/ 4100' 4000' (tag). PUH to 1990', plug #4 -
- spot 25 sxs f/ 1990' 1890'. PUH to 458', plug #5 spot 25 sxs f/ 458' 358' (tag). POH, plug #6- spot as surface plug. Cut off csg head, weld on plate & P&A marker.
- 3.

NOTE: Use 12.5 ppg gelled brine to displace with.

If 5-1/2" csg is pulled. Spot 50' in/50' out stump plug. Continue setting plugs.

## SEE ATTACHED FOR CONDITIONS OF APPROVAL

				and the second
14. I hereby certify that the foregoing is true and correct Name ( <i>Printed/Typed</i> )	Title	Regulatory Analyst		
Kim Stewart	The	Regulatory Allaryst		
Signature Kunnet	Date	11/20/02		
APPROVEL HIS SPACE FOR FEDERAL OR	STATE	OFFICE USE		
Approved by the States Provide Band States	Title		Date	
Conditions of approval (Many, are attached) Approval of this notice does not warrant or Certify that the applicant holds legal or equitable title to those rights in the subject lease Whick would entitle the applicant to conduct operations thereon.	Office			Ke
Title 18 U.S.C. Section DOI and The 33 U.S.C. Section 1212, Make it a crime for any pu United State any flase, ficturous or fraudulent statements or representations as to any matter	erson kno er within i	wingly and willfully to make to its jurisdiction.	any department of	r agency of the

		,		
		,	ŕ	



.; **н** 



a de la companya de l