11

## State of New Mexico Ene. , Minerals and Natural Resources Department

Form C-103 Revised 1-1-89

DISTRICT I P.O. Box 1980, Hobbs, NM 88240 **OIL CONSERVATION DIVISION** 

2040 Pacheco St.

DISTRICT II P.O. Drawer DD, Artesia, NM 88210 2040 Pacheco St. Santa Fe, NM 87505 WELL API NO. 30-025-35483

strate Cit Cool see No.

DISTRICT III «State Oil & Gas Lease No. 1000 Rio Brazos Rd., Aztec, NM 87410 E-1923 SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A Lease Name or Unit Agreement Name DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" Jeannie State (FORM C-101) FOR SUCH PROPOSALS.) Type of Well: GAS WELL WELL X OTHER «Well No. 2Name of Operator Trilogy Operating, Inc Address of Operator Pool name or Wildcat P.O. Box 7606, Midland, Texas 79708 **Eumont Y-SR-Q** ₄Well Location 660 South 1980 Feet From The Unit Letter Line and Feet From The Line 18 **20S** Section 36E Lea Range **NMPM** County 10Elevation (Show whether DF, RKB, RT, GR, etc.) 3652 GR

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:				SUBSEQUENT REPORT OF:			
PERFORM REMEDIAL WORK		PLUG AND ABANDON		REMEDIAL WORK		ALTERING CASING	
TEMPORARILY ABANDON		CHANGE PLANS		COMMENCE DRILLING OPNS.		PLUG AND ANBANDONMEN	п 🗀
PULL OR ALTER CASING				CASING TEST AND CEMENT JOB			
OTHER:			OTHER: Test Queen and Seven Rivers Formations		X		
				<del></del>			

12Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 7/23/01 RIH w/ Tbg Conveyed Stim-gun and perforate Queen Formation from 4054'-4058' w/ 6 spf or 24 holes , swab test and recover a skim of oil w/ formation on vacuum , no fluid entry SWION to check fluids overnight
- 7/24/01 RIH w/ swab and recover 50' of water , Set CIBP @ 4040' , perforate Seven Rivers Formation from 3912'-3922' & 3928'-3932' w/ Stim-gun , total holes = 84 , RU swab and swab well dry no fluid entry
- 7/25/01 Acidize Seven Rivers perforations w/ 1000 gals 7 1/2% NEFE + 20% MEOH, RU swab and recover flush only , no fluid entry after acid breakdown
- 7/27/01 SWI over weekend , no fluid entry , no shows of oil or gas , release rig prepare to plug & abandon

I hereby certify that the information above is true and complete to the best of my kind of the state of the best of my kind of the state of the best of my kind of the state of the best of my kind of the state of the best of my kind of the state of the best of my kind of the state of the best of my kind of the state of the best of my kind of the state of the best of my kind of the best of the best of my kind of the best	· ·	DATE 08-01-01
TYPE OR PRINT NAME Michael G. Mooney		TELEPHONE NO. 915/686-2027
(This space for State Use)	Oxig. Vizona sy Rem Ke <b>niz</b>	
APPROVED BY	TITLE Geologist	DATE