Submit 3 Copies To Appropriate District Office	State of New Mexico	Form C-103
District '	y, Minerals and Natural Resources	Revised March 25, 1999 WELL API NO.
1625 N. French Dr., Hobbs, NM 88240 District II		30025-35778
811 South First, Artesia, NM 88210 OIL	CONSERVATION DIVISION	5. Indicate Type of Lease
District III 1000 Rio Brazos Rd., Aztec, NM 87410	2040 South Pacheco	STATE FEE
District IV	Santa Fe, NM 87505	6. State Oil & Gas Lease No.
2040 South Pacheco, Santa Fe, NM 87505		
SUNDRY NOTICES AND R (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL DIFFERENT RESERVOIR. USE "APPLICATION FOR P PROPOSALS.)	L OR TO DEEPEN OR PLUG BACK TO A	7. Lease Name or Unit Agreement Name:
1. Type of Well: Oil Well Gas Well Gothe	r	Manzanita State
2. Name of Operator	1.11	8. Well No.
Concho Oil & Gas Corp.	WINTNIAL	2
3. Address of Operator	CONLINE	9. Pool name or Wildcat
110 W. Louisiana Ste 410; Midland, Tx 79701	001.5	Featherstone Bone Spring
4. Well Location		
Unit Letter D: 660 feet from the North line and 660 feet from the West line		
Section 16 Township 20S Range 35E NMPM Lea County		
10. Elevation (Show whether DR, RKB, RT, GR, etc.)		
3699' GR  11. Cheek Appropriate Poy to Indicate Nature of Natice Penert or Other Date		
11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data  NOTICE OF INTENTION TO:  SUBSEQUENT REPORT OF:		
PERFORM REMEDIAL WORK PLUG AND		
TEMPORARILY ABANDON		RILLING OPNS. PLUG AND
		ABANDONMENT
PULL OR ALTER CASING		AND L
OTHER:	☐ OTHER: comp	pletion
12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date		
of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.		
·		
01-24-02 NU 3000# manual BOP, tallied tbg.		
01-25-02 TIH w/ 4-3/4" bit, csg scraper & 2-7/8" tbg. Tagged PBTD @ 10814'. 01-26-02 MIRU & run GR/CBL from PBTD (WL: 10814') to 7800'. TOC @ 2050'. Perf w/ 2 SPF @ 10714-70724' (21 holes).		
01-28-02 TIH w/ pkr, SN & tbg. Set pkr @ 10597'. Tested pkr to 500# okay.		
01-29-02 Swabbing well. 01-30-02 Acid perfs w/ Bullhead 2000 gals 15% NEFE aicd. Begin swabbing.		
02-01-02 Unset pkr & TOH. Perf @ 10430-10450' w/ 2 SPF (42 holes). TIH w/ 5-1/2" RBP, pkr, SN & tbg. Set & test RbP @		
10510'. Tested to 1000# okay. Unset pkr @ 10497' & move to 10303'. Load annulus w/ 2% KCL tested pkr to 500#		
okay. 02-02-02 Testing perfs @ 10430-10450'. Swabbing.		
02-04-02 MIRU and acidize w/ 4000 gals 15% NEFE acid w/ 60 BS. Flowed back & died. RU & swab.		
02-08-02 Acid frac perfs @ 10430-10450' w/ 10000 gals gelled 20% acid. Flowed back & died. Begin swabbing.		
02-12-02 Unset pkr & TIH latch & unset RBP @ 10514'. Reset RBP @ 10402'. POOH w/ pkr. RU & perf @ 10376-10386' w/ 2 SPF (21 holes). RD. TIH w/ pkr SN & 315 jts tbg. Set pkr @ 10303'.		
02-13-02 Acid perfs w/ 4000 gals 15% NEFE. Swabbing well.		
02-16-02 Unset pkr @ 10303'. PU tbg. Fish 5-1/2" BP @ 10303'. TOH w/ tbg LD pkr & RBP. TIH w/ prod BHA, perf sub, SN,		
tbg, & TAC. ND BOP. NU tbg. Set TAC @ 10335'. RIH w/ rods & pump.  02-20-02 Turned well on @ 10:00 am.		
03-02-02 IP: 86 BO 72, BW, 25 MCF.		
I hereby certify that the information above is true and complete to the best of my knowledge and belief.		
1111 ///		
SIGNATURE Type or print name Terri Stathem	TITLE Production An	<del></del>
(This space for State use) APPPROVED BY		· レヘリエブ
Conditions of approval, if any:	TTTEE	M ENGINEER MARA 2 6 2002