WELL APINO   South Packers   South   Well   South   South   South   Well   South   South   South   Well   South   So	Submit 3 Copies To Appropriate District Office	State of New M		Form C-103 Revised March 25, 1999			
101 CUDERCY TION TO INTO INTO INTO INTO INTO INTO I	District I 1625 N. French Dr., Hobbs, NM 87240	Energy, Minerals and Natural Resources		WELL API NO.			
Sasta   Sast		OIL CONSERVATION	N DIVISION		-CI		
South Practices, NM 8740   Santa Fe, NM 87505   G. State Oil & Gas Lease No.	88210	2040 South Pac	heco	1			
Substitution   Subs	1000 Rio Brazos Rd., Aztec, NM 87410	Santa Fe, NM 8	7505				
SUNDRY NOTICES AND REPORTS ON WELLS    DO NOT USE THIS PORM FOR PROPOSALS TO DRILL OR TO DEPEND OR PLUG BACK TO A DIFFERENT RESERVOR. USE "APPLICATION FOR PERMIT" (PORM C-101) FOR SUCH   PROPOSALS TO REPORT		5					
2. Name of Operator Matador Operator Matador Operator S340 Meadow Road #150, Dallas, TX 75231  3. Address of Operator S340 Meadow Road #150, Dallas, TX 75231  4. Well Location  700  Unit Letter P	SUNDRY NOT (DO NOT USE THIS FORM FOR PROPORTION OF THE PROPOSALS.)  1. Type of Well:	FICES AND REPORTS ON WELL OSALS TO DRILL OR TO DEEPEN OR PI ICATION FOR PERMIT" (FORM C-101) F	LUG BACK TO A				
Mandor Operating Company   1   3. Address of Operator   9. Pool name or Wildcat   9. Pool name or Wildcat   Monument: Drinkard   4. Well Location   900   10. Elevation (Show whether DR, RKB, RT, GR, etc.)   10. Elevation (Show whether DR, RKB, RT, GR, etc.)   3556 GR   11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data   NOTICE OF INTENTION TO:   SUBSEQUENT REPORT OF:   PERFORM REMEDIAL WORK   PLUG AND ABANDON   REMEDIAL WORK   ALTERING CASING   COMMENCE DRILLING OPNS.   PLUG AND ABANDON   CHANGE PLANS   COMMENCE DRILLING OPNS.   PLUG AND ABANDON   CHANGE PLANS   COMMENCE DRILLING OPNS.   PLUG AND ABANDON   CHANGE PLANS   COMMENCE DRILLING OPNS.   PLUG AND ABANDON   CEMENT JOB   COMMENCE DRILLING OPNS.   PLUG AND ABANDON   OTHER:		Other	<del></del>	8 Well No			
3. Address of Operator   8340 Meadew Road #150, Dallas, TX 75231   9. Pool name of Wildcat   8340 Meadew Road #150, Dallas, TX 75231   9. Pool name of Wildcat   9. Monument: Drinkard   9. Woll Location   9. Woll Location   9. Woll Location   9. Section   9. Feet from the   South   line and   330   feet from the   East   line   10. Elevation (Show whether DR, RKB, RT, GR, etc.)   3356 GR   11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data   NOTICE OF INTENTION TO:   PERFORM REMEDIAL WORK   PLUG AND ABANDON   REMEDIAL WORK   PLUG AND ABANDON   REMEDIAL WORK   ALTERING CASING   PULL OR ALTER CASING   MULTIPLE   COMPLETION   CASING TEST AND   CEMENT JOB   OTHER:		,		3. Well No.			
Unit Letter P :	3. Address of Operator			1			
Unit Letter P		allas, TX 75231		Monument; l	Drinkard		
Section 5 Township 20S Range 37E NMPM Lea County  10. Elevation (Show whether DR, RKB, RT, GR, etc.) 3356' GR  11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON CHANGE PLUG AND ABANDON CHANGE PLUG AND ABANDON CHANGE PLUG AND ABANDON CHANGE PLUG AND ABANDONMENT CHANGE PLUG AND ABANDONMENT CHANGE POPPOSED COMPLETION CEMENT JOB  OTHER:  COMPLETION CHANGE PLUG ID THERE COMPLETION CEMENT JOB  OTHER:  DITIL 7-1/8" hole to 6800'. Logged well. Ran DSN-SDL-LSS-DLL-MSFL. Ran 162 jts. of 4-1/2" 11.6# N-80 LTC casing on 3/4/02 (set @ 6800'). Cement 18 stage w/585 sx Super "H" + 4/10% CFR.3 + 5/10% Halad 344 + 3# Salt + 5# Gilsonite (wt. 13.0 ppg – yld 1.66). Displace w/FW below DV Tool. Land plug w/500 psi over. Drop bomb; poen DV Tool. Circulate It lis sx to pit. Cement 26 stage w/580 sh (Created Stages) and plug w/500 psi over. Drop bomb; poen DV Tool. Circulate It lis sx to pit. Cement 26 stage w/583 sx Ruper "H" + 4/10% CFR.3 + 5/10% Halad 322. Follow w/182 sx Interfill "C" + 1/4# Flocele (wt. 11.5 ppg – yld 2.73). Tail w/100 sx Class "C" Neat (wt. 14.8 ppg – yld 1.32). Land plug w/2440 psi. Close DV Tool. Bleed off. Did not offclus apment.  Set slips w/77,000#. Install wellhead. Released rig 3/4/02.  Thereby certify that the information above is true and complete to the best of my knowledge and belief.  SIGNATURE Amanda Amanda Complete to the best of my knowledge and belief.  TITLE Regulatory Analyst DATE 5 1/4/102  Type or print name Sharon Cook  Telephone No. 214-987-7174	4. Well Location	900					
10. Elevation (Show whether DR, RKB, RT, GR, etc.)  3356 GR  11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO:  PERFORM REMEDIAL WORK PLUG AND ABANDON COMMENCE DRILLING OPNS. ALTERING CASING ABANDON CHANGE PLUG AND ABANDON CEMENT JOB  PULL OR ALTER CASING MULTIPLE COMPLETION CEMENT JOB  OTHER: CASING TEST AND CEMENT JOB  OTHER: THERE COMPLETION CHANGE PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB  OTHER: THERE COMPLETION CHANGE PLUG AND ABANDONMENT COMPLETION CEMENT JOB  OTHER: THERE CASING CHANGE PLUG AND ABANDONMENT COMPLETION CEMENT JOB  OTHER: THERE CASING CHANGE PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB  OTHER: THERE CASING CHANGE PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB  OTHER: THERE CASING CHANGE PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB  OTHER: THERE CASING CHANGE PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB  OTHER: THERE CASING CHANGE PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB  OTHER: THERE CASING CHANGE PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB  OTHER: THERE CASING CHANGE PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB  OTHER: THE CASING CHANGE PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB  OTHER: THE STAND CASING TEST AND CASING TEST AND CEMENT JOB ABANDONMENT CASING TEST AND CASING TEST AND CEMENT JOB ABANDONMENT CASING TEST AND CEMENT JOB ABANDONMENT CASING TEST AND CA	Unit Letter P	: _ <del>500</del> feet from theSo	uth line and	feet from	the <u>East</u> line		
10. Elevation (Show whether DR, RKB, RT, GR, etc.)  3356' GR  11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data  NOTICE OF INTENTION TO:  PERFORM REMEDIAL WORK   PLUG AND ABANDON   REMEDIAL WORK   ALTERING CASING    TEMPORARILY ABANDON   CHANGE PLANS   COMMENCE DRILLING OPNS.   PLUG AND ABANDONMENT    PULL OR ALTER CASING   MULTIPLE   CASING TEST AND CEMENT JOB    OTHER:   OTHER	Section 5	Township 20S	Range	37F NMPM	Lea County		
11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO:  PERFORM REMEDIAL WORK   PLUG AND ABANDON   REMEDIAL WORK   ALTERING CASING    TEMPORARILY ABANDON   CHANGE PLANS   COMMENCE DRILLING OPNS.   PLUG AND ABANDONMENT    PULL OR ALTER CASING   MULTIPLE   CASING TEST AND CEMENT JOB    OTHER:   THIRD TH	Section				Eca County		
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK   PLUG AND ABANDON   REMEDIAL WORK   ALTERING CASING    TEMPORARILY ABANDON   CHANGE PLANS   COMMENCE DRILLING OPNS.   PLUG AND ABANDONMENT    PULL OR ALTER CASING   MULTIPLE   COMPLETION   CASING TEST AND CEMENT JOB    OTHER:   OTHER:							
PERFORM REMEDIAL WORK PLUG AND ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. ABANDONMENT COMMENT COMMENT DRILLING OPNS. ABANDONMENT COMMENT DRILLING OPNS. COMMEN							
TEMPORARILY ABANDON					,		
PULL OR ALTER CASING MULTIPLE COMPLETION CEMENT JOB  OTHER: OTHER: OTHER:  12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.  • Drill 7-7/8" hole to 6800". Logged well. Ran DSN-SDL-LSS-DLL-MSFL.  • Ran 162 jts. of 4-1/2" 11.6# N-80 LTC casing on 3/4/02 (set @ 6800"). Cement 1" stage w/585 sx Super "H" + 4/10% CFR-3 + 5/10% Halad 344 + 3# Salt + 5# Gilsonite (wt. 13.0 ppg - yld 1.66). Displace w/FW below DV Tool. Land plug w/500 psi over. Drop bomb; open DV Tool. Circulalte 118 sx to pit. Cement 2nd stage w/433 sx Interfill "C" + 1/4# Flocele (wt 11.5 ppg - yld 2.73). Tail w/100 sx Class "C" Neat (wt. 14.8 ppg - yld 1.32). Land plug w/2440 psi. Close DV Tool. Bleed off. Did not of a land a complete to the best of my knowledge and belief.  Set slips w/77,000#. Install wellhead. Released rig 3/4/02.  Thereby certify that the information above is true and complete to the best of my knowledge and belief.  SIGNATURE TITLE Regulatory Analyst DATE 3/14/10.2  Type or print name Sharon Cook Telephone No. 214-987-7174		_					
OTHER:    OTHER:		_			1 1		
12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.  • Drill 7-7/8" hole to 6800'. Logged well. Ran DSN-SDL-LSS-DLL-MSFL.  • Ran 162 jts. of 4-1/2" 11.6# N-80 LTC casing on 3/4/02 (set @ 6800'). Cement 1st stage w/585 sx Super "H" + 4/10% CFR-3 + 5/10% Halad 344 + 3# Salt + 5# Gilsonite (wt. 13.0 ppg – yld 1.66). Displace w/FW below DV Tool. Land plug w/500 psi over. Drop bomb; open DV Tool. Circulate 118 sx to pit. Cement 2nd stage w/433 sx Interfill "C" + 1/4# Flocele (wt. 11.5 ppg – yld 2.73). Tail w/100 sx Class "C" Neat (wt. 14.8 ppg – yld 1.32). Land plug w/2440 psi. Close DV Tool. Bleed off. Did net or child competent.  • Set slips w/77,000#. Install wellhead. Released rig 3/4/02.  Thereby certify that the information above is true and complete to the best of my knowledge and belief.  SIGNATURE TITLE Regulatory Analyst DATE 3/14/02  Type or print name Sharon Cook Telephone No. 214-987-7174	PULL OR ALTER CASING L						
of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.  • Drill 7-7/8" hole to 6800'. Logged well. Ran DSN-SDL-LSS-DLL-MSFL.  • Ran 162 jts. of 4-1/2" 11.6# N-80 LTC casing on 3/4/02 (set @ 6800'). Cement 1st stage w/585 sx Super "H" + 4/10% CFR-3 + 5/10% Halad 344 + 3# Salt + 5# Gilsonite (wt. 13.0 ppg – yld 1.66). Displace w/FW below DV Tool. Land plug w/500 psi over. Drop bomb; open DV Tool. Circulalte 118 sx to pit. Cement 2nd stage w/433 sx Interfill "C" + ½# Flocele + 3# Gilsonite + 2/10% Halad 322. Follow w/182 sx Interfill "C" + ½# Flocele wt 11.5 ppg – yld 2.73). Tail w/100 sx Class "C" Neat (wt. 14.8 ppg – yld 1.32). Land plug w/2440 psi. Close DV Tool. Bleed off. Did not or call section.  • Set slips w/77,000#. Install wellhead. Released rig 3/4/02.  Thereby certify that the information above is true and complete to the best of my knowledge and belief.  SIGNATURE TITLE Regulatory Analyst DATE 3/14/02  Type or print name Sharon Cook Telephone No. 214-987-7174	OTHER:		OTHER:				
• Ran 162 jts. of 4-1/2" 11.6# N-80 LTC casing on 3/4/02 (set @ 6800'). Cement 1st stage w/585 sx Super "H" + 4/10% CFR-3 + 5/10% Halad 344 + 3# Salt + 5# Gilsonite (wt. 13.0 ppg – yld 1.66). Displace w/FW below DV Tool. Land plug w/500 psi over. Drop bomb; open DV Tool. Circulalte 118 sx to pit. Cement 2nd stage w/433 sx Interfill "C" + 1/4# Flocele + 3# Gilsonite + 2/10% Halad 322. Follow w/182 sx Interfill "C" + 1/4# Flocele (wt 11.5 ppg – yld 2.73). Tail w/100 sx Class "C" Neat (wt. 14.8 ppg – yld 1.32). Land plug w/2440 psi. Close DV Tool. Bleed off. Did not off the complete to the best of my knowledge and belief.  • Set slips w/77,000#. Install wellhead. Released rig 3/4/02.  Title Regulatory Analyst DATE 3/14/02  Type or print name Sharon Cook Telephone No. 214-987-7174	of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion						
I hereby certify that the information above is true and complete to the best of my knowledge and belief.  SIGNATURE  TITLE Regulatory Analyst  DATE 3/14/02  Type or print name  Sharon Cook  Telephone No. 214-987-7174	<ul> <li>Ran 162 jts. of 4-1/2" 11.6# N-80 LTC casing on 3/4/02 (set @ 6800"). Cement 1st stage w/585 sx Super "H" + 4/10% CFR-3 + 5/10% Halad 344 + 3# Salt + 5# Gilsonite (wt. 13.0 ppg - yld 1.66). Displace w/FW below DV Tool. Land plug w/500 psi over. Drop bomb; open DV Tool. Circulalte 118 sx to pit. Cement 2nd stage w/433 sx Interfill "C" + 1/4# Flocele + 3# Gilsonite + 2/10% Halad 322. Follow w/182 sx Interfill "C" + 1/4# Flocele (wt 11.5 ppg - yld 2.73). Tail w/100 sx Class "C" Neat (wt. 14.8 ppg - yld 1.32). Land plug w/2440 psi. Close DV Tool. Bleed off. Did not circulate coment.</li> <li>Set slips w/77,000#. Install wellhead. Released rig 3/4/02.</li> </ul>						
SIGNATURE Sharon Cook Telephone No. 214-987-7174				·			
Type or print name Sharon Cook Telephone No. 214-987-7174							
	SIGNATURE Shir C	TITLE_	Regulatory A	nalyst	DATE 3/14/02		
	Type or print name Shar	Type or print name Sharon Cook Telephone No. 214-987-7174					
APPPROVED BY TITLE ORIGINAL SIGNAL STATE DATE MAR 1 9 2002  Conditions of approval, if any:  PETROLEUM ENGINEER				L CIGNED BY			
Conditions of approval, if any:  PETROLEUM ENGINEER  PAUL 1.1. ENGINEER	APPPROVED BY	דודו ד	ORIGINA	F KAUTZ	DATE MAR 1 9 2002		
			PETROL	EUM ENGINEER			

ていること