

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

P.O. Box Drawer DD, Artesia, NM 88210

DISTRICT III

1000 R o Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088

Santa Fe, New Mexico 87504-2088

WELL API NO.	3002506058
5. Indicate Type of Lease	STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil / Gas Lease No.	830140
7. Lease Name or Unit Agreement Name	WEIR, C. H. -B-
8. Well No.	1
9. Pool Name or Wildcat	SKAGGS DRINKARD
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	

SUNDRY NOTICES AND REPORTS ON WELL  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:	OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER
2. Name of Operator	TEXACO EXPLORATION & PRODUCTION INC.
3. Address of Operator	205 E. Bender, HOBBS, NM 88240
4. Well Location	Unit Letter <u>H</u> : <u>1984</u> Feet From The <u>NORTH</u> Line and <u>660</u> Feet From The <u>EAST</u> Line Section <u>11</u> Township <u>20S</u> Range <u>37E</u> NMPM <u>LEA</u> COUNTY

11.

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK	<input type="checkbox"/>	PLUG AND ABANDON	<input type="checkbox"/>
TEMPORARILY ABANDON	<input type="checkbox"/>	CHANGE PLANS	<input type="checkbox"/>
PULL OR ALTER CASING	<input type="checkbox"/>		
OTHER:	<input type="checkbox"/>		

SUBSEQUENT REPORT OF:

REMEDIAL WORK	<input checked="" type="checkbox"/>	ALTERING CASING	<input type="checkbox"/>
COMMENCE DRILLING OPERATION	<input type="checkbox"/>	PLUG AND ABANDONMENT	<input type="checkbox"/>
CASING TEST AND CEMENT JOB	<input type="checkbox"/>		
OTHER:	<input type="checkbox"/>		

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

2-17-98: MIRU. BLOW DN TO BTRY. LEFT FLOWING.  
2-18-98: KILL WELL W/40 BBLS WTR. NDWH. NUBOP. TOH W/2 3/8" TBG.  
2-19-98: RAN BIT & BAILER ON 2 3/8" TBG. C/O FR 6852-6898' (PBTD). RECVD FRAC SD. RAN PERF CLEAN TOOL ON TBG. WSHD & ACIDIZED 5 1/2" CSG PERFS 6605-6870' W/180 BBLS 2% KCL FW & 3200 GALS 15% NEFRE ACID.  
2-20-98: SWAB. TOH W/PERF CLEAN TOOL. TIH W/SN, 210 JTS 2 3/8" TBG. SN @ 6825'. WELL ON PLUNGER LIFT & TESTING. RIG DOWN.  
4-25-98: ON 24 HR OPT. PUMPED 2 BO, 5 BW, & 55 MCF.  
FINAL REPORT

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE J. Denise Leake TITLE Engineering Assistant DATE 6/3/98  
TYPE OR PRINT NAME J. Denise Leake Telephone No. 397-0405

(This space for State Use)

APPROVED BY Paul Kaula TITLE Geologist DATE 6/3/98

CONDITIONS OF APPROVAL, IF ANY: