Submit 3 copies to Appropriate District Office

State of New Mexico y, Minerals and Natural Resources Department

Form C-103 Revised 1-1-89

DISTRICT

DICTITION		OIL CONSERV	7 A TT	ON DIVICION		······································		
P.O. Box 1980, Hobbs, NM	88240				WELL API NO).		
STRICT II			Box 208	30 025 06073				
J. Box Drawer DD, Artesia, NM 88210 Santa Fe, New Mexico 87504-2088					5. Indicate Ty	·	eee K	
DISTRICT III						STATE	FEE 🛛	
1000 Rio Brazos Rd., Aztec, I	NM 87410				6. State Oil /	Gas Lease No.		
SU	JNDRY NOT	TICES AND REPORTS	ON WE	LL				
(DO NOT USE THIS FOR	(M FOR PRO	POSALS TO DRILL OR TO	DEEPE	N OR PLUG BACK TO A	7. Lease Nan	ne or Unit Agreement Name		
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)					CH WEIR			
Type of Well: OIL WELL	GAS	П						
	WELL	OTHER						
2. Name of Operator	TEXACO EXF	PLORATION & PRODUCTION	ON INC.		8. Well No.	7		
3. Address of Operator P.O. BOX 730, HOBBS, NM 88240						9. Pool Name or Wildcat		
4. Well Location					L	SKAGGS DRINKARD		
Unit Letter	 :	1985 Feet From The	sou	TH Line and 660	_ Feet From	The <u>WEST</u> Line		
Section 12		Township 20S	F	Range <u>37E</u> NM	РМ	LEA_ COUNTY		
		10. Elevation (Show whether	DF, RKB,	RT,GR, etc.) 3578' DF				
11.	Check Ap	propriate Box to Indic	ate Na	ture of Notice, Report	, or Other I	Data		
MOTIOT OF WITH MICH.					JBSEQUENT REPORT OF:			
PERFORM REMEDIAL WORK	С П	PLUG AND ABANDON		REMEDIAL WORK		ALTERING CASING	$\overline{}$	
TEMPORARILY ABANDON	Ä	CHANGE PLANS	$\overline{\Box}$	COMMENCE DRILLING OPE		PLUG AND ABANDONMENT	片	
PULL OR ALTER CASING	H		لبنا	CASING TEST AND CEMEN				
OTHER:			П	OTHER:				
` Describe Proposed or Col work) SEE RULE 1103.	mpleted Opera	ations (Clearly state all pertin	ent detail	s, and give pertinent dates, i	ncluding estin	nated date of starting any prop	osed	
10/11/93 - 10/22/93								
1. MIRU, TOH W/ PROD E	QUIP. C/O T	O 6814'.						
2. SET RBP @ 6503' & TST	D CSG TO 50	00#, OK. PERFD DRINKAR	RD W/ 2 .	JSPF FR 6837'- 6590' (34 IN	NT - 68 HLES).		
3. SET PKR @ 6506', ACID	IZED PERFS	W/ 3500 15% NEFE. MAX	P = 230#	, AIR = 7 BPM. SWABBED	BACK.			
4. FRACD SKAGGS DRK F MAX P=7600#, AIR=38 BI	R 6590'-6837' PM. TOH W/	W/ 67,000 GALS 30# X/L (PKR. TAGGED SAND @ 6	GEL, 228 5307', D/0	1,000# 20/40, & 60000# 12/2 O TO 6837'.	0 SAND.			

- 5. RETURNED WELL TO PRODUCTION.

OPT 11/5/93 7 BOPD, 39 BWPD, 518 MCFD

APPROVED BY		TITLE_	DISTRICT I SUPERVISOR	DATE	APR 01 199
(This space for State Use)			ORIGINAL SIGNED BY JERRY SEXTON		400 0
TYPE OR PRINT NAME	Darrell J. Carriger			Telephone No.	397-0431
SIGNATURE Would Je	hor	TITLE	Engineering Assistant	DATE	3/10/94
I hereby certify that the information above is true and o	complete to the best of my knowledge and	belief.			