

OIL CONSERVATION DIVISION

P. O. BOX 2088

SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-77

NO. OF COPIES TO RECEIVERS	
CITY SECTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

3a. Indicate Type of Lease	
State ☐	Fee ☐
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

OIL WELL ☒	GAS WELL ☐	OTHER ☐	7. Unit Agreement Name
Name of Operator			8. Farm or Lease Name
Texaco Inc.			C. H. Weir "A"
Address of Operator			9. Well No.
P. O. Box 728, Hobbs, NM 88240			8
Location of Well			10. Field and Pool, or WHdcn
UNIT LETTER <u>F</u> 1980 FEET FROM THE <u>West</u> LINE AND 1985 FEET FROM			Skaggs Drinkard, Weir
THE <u>North</u> LINE, SECTION <u>12</u> TOWNSHIP <u>20S</u> RANGE <u>37E</u> NMPM.			Blinbry East Monument Tub
15. Elevation (Show whether DF, RT, GR, etc.)			12. County
3574' DF			Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☐
NULL OR ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT JOB ☐	OTHER <u>P&A Drinkard Zone and segregated</u> ☒
		downhole commingle.	

7. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 1) MIRUPU. From Weir Blinbry East string, TOH w/rods and pump.
- 2) Hot oiled tbg. w/100 BO. TOH w/ 2 1/16" tbg.
- 3) By wireline, ran gauge ring to 6700'. TOH. Ran 2 7/8" CIBP and set @ 6665'.
- 4) Killed Monument Tubb & Skaggs Drinkard string. Ran gauge ring to 6700'. TOH. Ran 2 7/8" CIBP and set @ 6665'.
- 5) With dump bailer, dumped 30' cmt. on CIBP in Weir Blinbry East string. PBTD 6635'. Couldn't get dump bailer into Monument Tubb - Skaggs Drinkard string.
- 6) TIH w/Weir Blinbry East production tbg. and pump. POB. Monument Tubb gas turned on to El Paso sales. RDPU on 6/14/86.
- 7) Skaggs Drinkard formation is now abandoned due to low production and inability to effectively isolate for additional work.
- 8) Weir Blinbry East and Monument Tubb returned to production as single completions.

8. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

CHECKED JW Browning TITLE District Admin. Supervisor DATE 06/25/86ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT 1 SUPERVISORAPPROVED BY _____ TITLE _____ DATE JUL 2 1986

CONDITIONS OF APPROVAL, IF ANY:

2 A Skaggs Drinkard