OTHER MADE PLANS OTHER SERVICE AND ADARDON Check Appropriate Box To Indicate Nature of Notice, Report of Other Data NOTICE OF INTENTION TO: PLANCE PLANS OTHER CASHOC COMMERCE OR INLING OTHER OTHER OTHER OTHER COMMERCE OR INLING OTHER OT	DISTRIBUTION	1 1	Form C-103
SUNDRY NOTICES AND REPORTS ON WELLS SUNDRY NOTICES OF THE SUNDRY NOTICES ON WELLS SUNDRY NOTICES OF THE SUNDRY NOTICES ON WELLS SUNDRY NOTICES OF THE SUNDRY NOTICE OF THE SUNDRY		 	
Substitute Sub		NEW MEXICO OIL CONSERVATION COMMIS	
LAND OFFICE OPERATOR SUNDRY NOTICES AND REPORTS ON WELLS OPERATOR SUNDRY NOTICES AND REPORTS ON WELLS OPERATOR SUNDRY NOTICES AND REPORTS ON WELLS OPERATOR OPERATOR SUNDRY NOTICES AND REPORTS ON WELLS OPERATOR OPERATOR OPERATOR OPERATOR SUNDRY NOTICES AND REPORTS ON WELLS OPERATOR OPERATOR	FILE		
SUNDRY NOTICES AND REPORTS ON WELLS ONLY OF THE THIS FORWARD CONTROL OF THE SHAPE			5a. Indicate Type of Lease
SUNDRY NOTICES AND REPORTS ON WELLS OR NOT JEE THIS FEW PARTICLES AND REPORTS ON WELLS OF THE THIS FEW PARTICLES AND REPORTS ON WELLS OF THE THIS FEW PARTICLES AND REPORTS ON WELLS OF THE THIS FEW PARTICLES AND REPORTS ON WELLS OF THE THIS FEW PARTICLES AND REPORTS ON WELLS OF THE THIS FEW PARTICLES AND REPORTS ON WELLS PARTICLES AND REPORTS ON THE THIS FEW PARTICLES AND REPORTS ON WELLS TRACE OF THE THIS FEW PARTICLES AND REPORTS ON WELLS PARTICLES AND REPORTS ON THE THIS FEW PARTICLES AND REPORTS OF THE THIS F	LAND OFFICE		State Fee. 🗶
To Describe Proposed of Completed Operations (Clearly state all pertinent desits, and give pertinent dates, including estimated date of starting any proposed work year of the Labor Police of National Police of States and Complete Completed Control of National Police of National	OPERATOR		5. State Oil & Gas Lease No.
The continue of Secretary Continues and Continues are all personal dates, including estimated date of storting any proposed works of sequences (present than the continue of Secretary Continues). The continue of Secretary Continues are all personal transformation of Secretary Continues and Continues are all personal transformations. The continues of Secretary Continues are all personal transformations and the continues are all personal transformations. The continues are all personal transformations and transformations are all personal transformations. The continues are all personal transformations and transformations. The continues are all personal transformations and transformations. The continues are all personal transformations and transformations are all personal transformations. The continues are all personal transformations and transformations are all personal transformations. The continues are all personal transformations and transformations and transformations are all personal transformations. The continues are all personal transformations and transformations are all personal transformations and transformations. The continues are all personal transformations and transformations are all personal transformations. The continues are all personal transformations and transformations are all personal transformations. The continues are all personal transformations and transformations are all personal transformations. The continues are all personal transformations and transformations are all personal transformations. The continues are all personal transformations are all personal transformations. The continues are all personal transformations are all personal transformations. The continues are all personal transformations are all personal transformations. The continues are all personal transformations are all per	SL (DO NOT USE THIS FORM F	JNDRY NOTICES AND REPORTS ON WELLS	SERVOIR ANNUAL SERVOIR
Skaggs Grayburg Unit Skaggs Grayburg 12. Central No. Skaggs Grayburg Unit Skaggs Grayburg In February Inc. Skaggs Grayburg In February In February Skaggs Grayburg In February In February In February Skaggs Grayburg In February Skaggs Grayburg In February In February Skaggs Grayburg In February Skaggs Grayburg In February Skaggs Grayburg In February Skaggs Grayburg In February In February Skaggs Grayburg In February In February Skaggs Grayburg In February Skaggs Grayburg In February Skaggs Grayburg In February Skaggs In Februar	<u></u>		
Skaggs Grayburg Unit S. Addieses of Directors P.O. BOX 728 - HOBBS, NEW MEXICO 88240 S. Location of Weil Line And Directors West		OTHER- INJECTION WELL	Skaggs Grayburg Unit
P.O. BOX 728 - HOBBS, NEW MEXICO 88240 12 A, Location of Well Out I Letter C 662 FEET FROM THE INCH 1980 Skaggs Grayburg 10. Field and Pool, or Wildcot Skaggs Grayburg 12. County Letter Skaggs Grayburg 13. Township Is. Elevation (Show whether Dr. RT, GR, etc.) Stages Grayburg 15. Elevation (Show whether Dr. RT, GR, etc.) The Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PLUE AND ABANDON COMMERCE BRILLING DRMS. COMMERCE B			
ALLOCATION (A Section of West Completed Control of West Completed Control of West Completed Control of Control o		BBS, NEW MEXICO 88240	9. Well No.
West 13 TOWNSHIP 20S RANGE STEET FROM THE LINE AND 37E NOPTH 15. Elevation (Show whether DF, RT, GR, etc.) 3566 'DF Lea NOTICE OF INTENTION TO: Check Appropriate Box To Indicate Nature of Notice, Report or Other Data Subsequent Report of: REMEDIAL WORK SUBSEQUENT REPORT OF: REMEDIAL WORK COVILING OTHER COMMERCE OF INTENTION TO: PERFORM REMEDIAL WORK ADDRESS OF AND ABANDON CHANGE PLANS OTHER COMMERCE OF INTENTION TO: PRINCE THE AND ABANDON CHANGE PLANS OTHER COMMERCE OF INTENTION TO: PRINCE THE PROPOSED OF COMMERCE OF INTENTION TO: REMEDIAL WORK SER RULE 1 (10). Pull tubing W/packer. Run tubing W/cement retainer set at 3700'. Squeeze open hole section w/100 sx. Class 'C' cement w/fluid loss additive. If necessary resqueeze w/another 100 sx cement. Drill out cement to 3870'. Perforate w/2 JSPF from 3/47-51', 3754-58', 3761-63', & 2 JSPI at 3786', 3812', 23', 30', 37', 42', 53' & 3968'. Actidize w/4000 gais 15% NEA in 10 equal stages. Add blocking material between stages. Run tubing w/packer set at 3700' and place on injection. Orig. Signed by Orig. Signed by	4. Location of Well	CCO	10. Field and Pool, or Wildcat
The Line, SECTION IS, Elevation (Show whether DF, RT, GR, COL.) 12. Country Lea 13. Elevation (Show whether DF, RT, GR, COL.) 12. Country Lea 13. Elevation (Show whether DF, RT, GR, COL.) 14. Country Lea 15. Elevation (Show whether DF, RT, GR, COL.) 16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: 16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data SUBSEQUENT REPORT OF: 16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data SUBSEQUENT REPORT OF: 16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data SUBSEQUENT REPORT OF: 16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data SUBSEQUENT REPORT OF: 16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data Country Lea Country L			Stange Chauhung
TOWNSHIP 15. Elevation (Show whether DF, RT, GR, etc.) Check Appropriate Box To Indicate Nature of Notice, Report or Other Data SUBSEQUENT REPORT OF: REMEDIAL WORK OTHER OTHER CHANGE PLANS OTHER OTHER CHANGE PLANS OTHER CHANGE PLANS OTHER OTHER OTHER CHANGE PLANS OTHER OTHER CHANGE PLANS OTHER OTHER OTHER OTHER CHANGE PLANS OTHER OT		13 205 37	
Check Appropriate Box To Indicate Nature of Notice, Report or Other Data Subsequent Report of Subsequent Report of: Perform Remedial Nork Remedial Nork Commence Official Nork Casing Test and cement reps Other Other There Other Remedial Nork Perform Remedial Nork Casing Test and cement reps Other Remedial Nork Casing Test and cement reps Casing Test and cement reps Casing Test and cement reps Other Remedial Nork Casing Test and cement reps	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	HANGE	NMPM.
Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PERFORM REMODIAL WORK TEMPORALITY ASARDON OTHER			
SUBSEQUENT REPORT OF: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK THEMPORABILY ASADON OTHER 7. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1703. Pull tubing W/cement retainer set at 3700'. Squeeze open hole section w/100 sx. Class 'C' cement w/fluid loss additive. If necessary resqueeze w/another 100 sx cement. Drill out cement to 3870'. Perforate w/2 JSPF from 3747-51', 3754-58', 3761-63', & 2 JSPI at 3786', 3812', 23', 30', 37', 42', 53' & 3868'. Acticize w/4000 gals 15% NEA in 10 equal stages. Add blocking material between stages. Run tubing w/packer set at 3700' and place on injection. I hereby certify that the information above is true and complete to the best of my knowledge and belief. Orig. Signed by	6. Che		
PROPORM REMEDIAL WORK TEMPORABILY ABANDON THER OTHER 7. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed under the proposed of th	NOTICE C		
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER 7. Describe Proposed or Completed Operations (Clearly state all persinent details, and give persinent dates, including estimated date of starting any proposed work) SEE RULE 1 (103). Pull tubing W/packer. Run tubing W/cement retainer set at 3700'. Squeeze open hole section w/100 sx. Class 'C' cement w/fluid loss additive. If necessary resqueeze w/another 100 sx cement. Drill out cement to 3870'. Perforate w/2 JSPF from 3747-51', 3754-58', 3761-63', & 2 JSPI at 3786', 3812', 23', 30', 37', 42', 53' & 3868'. Acidize w/4000 gals 15% NEA in 10 equal stages. Add blocking material between stages. Run tubing w/packer set at 3700' and place on injection. District Supt. January 12, 1972 Orig. Signed by	-₩ 1		SUBSEQUENT REPORT OF:
OTHER 7. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1703. Pull tubing w/cement retainer set at 3700'. Squeeze open hole section w/100 sx. Class 'C' cement w/fluid loss additive. If necessary resqueeze w/another 100 sx cement. Drill out cement to 3870'. Perforate w/2 JSPF from 3747-51', 3754-58', 3761-63', & 2 JSPI at 3786', 3812', 23', 30', 37', 42', 53' & 3868'. Acidize w/4000 gals 15% NEA in 10 equal stages. Add blocking material between stages. Run tubing w/packer set at 3700' and place on injection. 1 hereby certify that the information above is true and complete to the best of my knowledge and belief. TITLE Asst. District Supt. Orig. Signed by	PERFORM REMEDIAL WORK	PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING
OTHER OT	TEMPORARILY ABANDON	COMMENCE DRILLING O	
7. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE ROLE 1103. Pull tubing w/packer. Run tubing w/cement retainer set at 3700'. Squeeze open hole section w/100 sx. Class 'C' cement w/fluid loss additive. If necessary resqueeze w/another 100 sx cement. Drill out cement to 3870'. Perforate w/2 JSPF from 3747-51', 3754-58', 3761-63', & 2 JSPI at 3786', 3812', 23', 30', 37', 42', 53' & 3868'. Acidize w/4000 gals 15% NEA in 10 equal stages. Add blocking material between stages. Run tubing w/packer set at 3700' and place on injection. Asst. District Supt. Orig. Signed by	PULL OR ALTER CASING	CHANGE PLANS CASING TEST AND CEMI	
7. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE ROLE 1103. Pull tubing w/packer. Run tubing w/cement retainer set at 3700'. Squeeze open hole section w/100 sx. Class 'C' cement w/fluid loss additive. If necessary resqueeze w/another 100 sx cement. Drill out cement to 3870'. Perforate w/2 JSPF from 3747-51', 3754-58', 3761-63', & 2 JSPI at 3786', 3812', 23', 30', 37', 42', 53' & 3868'. Acidize w/4000 gals 15% NEA in 10 equal stages. Add blocking material between stages. Run tubing w/packer set at 3700' and place on injection.			
Pull tubing w/packer. Run tubing w/cement retainer set at 3700'. Squeeze open hole section w/100 sx. Class 'C' cement w/fluid loss additive. If necessary resqueeze w/another 100 sx cement. Drill out cement to 3870'. Perforate w/2 JSPF from 3747-51', 3754-58', 3761-63', & 2 JSPI at 3786', 3812', 23', 30', 37', 42', 53' & 3868'. Acidize w/4000 gals 15% NEA in 10 equal stages. Add blocking material between stages. Run tubing w/packer set at 3700' and place on injection. Asst. District Supt. Orig. Signed by		OTHER	
Pull tubing w/packer. Run tubing w/cement retainer set at 3700'. Squeeze open hole section w/100 sx. Class 'C' cement w/fluid loss additive. If necessary resqueeze w/another 100 sx cement. Drill out cement to 3870'. Perforate w/2 JSPF from 3747-51', 3754-58', 3761-63', & 2 JSPI at 3786', 3812', 23', 30', 37', 42', 53' & 3868'. Acidize w/4000 gals 15% NEA in 10 equal stages. Add blocking material between stages. Run tubing w/packer set at 3700' and place on injection. Asst. District Supt. Orig. Signed by	OTHER	OTHER	
Orig. Signed by Asst. District Supt. Orig. Signed by	7. Describe Proposed or Complet work) SEE RULE 1103.	ted Operations (Clearly state all pertinent details, and give pertinent	
Orig. Signed by Asst. District Supt. Orig. Signed by	7. Describe Proposed or Complet work) SEE RULE 1103. Pull tubing w/pac. Run tubing w/ceme. Squeeze open hole resqueeze w/anoth Drill out cement. Perforate w/2 JSP 37', 42', 53' & 3 Acidize w/4000 ga	cker. ent retainer set at 3700'. e section w/100 sx. Class 'C' cement w/fluer 100 sx cement. to 3870'. F from 3747-51', 3754-58', 3761-63', & 2868'. Its 15% NEA in 10 equal stages. Add block	dates, including estimated date of starting any proposed aid loss additive. If necessary JSPI at 3786', 3812', 23', 30',
Orig. Signed by	17. Describe Proposed or Complet work) SEE RULE 1103. Pull tubing w/pac. Run tubing w/ceme. Squeeze open hole resqueeze w/anoth. Drill out cement. Perforate w/2 JSP 37', 42', 53' & 3 Acidize w/4000 ga	cker. ent retainer set at 3700'. e section w/100 sx. Class 'C' cement w/fluer 100 sx cement. to 3870'. F from 3747-51', 3754-58', 3761-63', & 2868'. Its 15% NEA in 10 equal stages. Add block	dates, including estimated date of starting any proposed aid loss additive. If necessary JSPI at 3786', 3812', 23', 30',
Orig. Signed by	17. Describe Proposed or Complet work) SEE RULE 1103. Pull tubing w/pac. Run tubing w/ceme. Squeeze open hole resqueeze w/anoth. Drill out cement. Perforate w/2 JSP 37', 42', 53' & 3. Acidize w/4000 ga. Run tubing w/pack	ted Operations (Clearly state all pertinent details, and give pertinent exer. ent retainer set at 3700'. e section w/100 sx. Class 'C' cement w/fluter 100 sx cement. to 3870'. F from 3747-51', 3754-58', 3761-63', & 2868'. Is 15% NEA in 10 equal stages. Add blocker set at 3700' and place on injection.	dates, including estimated date of starting any proposed aid loss additive. If necessary JSPI at 3786', 3812', 23', 30', sing material between stages.
	7. Describe Proposed or Complet work) SEE RULE 1103. Pull tubing w/ceme. Run tubing w/ceme. Squeeze open hole resqueeze w/anoth. Drill out cement. Perforate w/2 JSP 37', 42', 53' & 3. Acidize w/4000 ga. Run tubing w/pack	ted Operations (Clearly state all pertinent details, and give pertinent cker. ent retainer set at 3700'. e section w/100 sx. Class 'C' cement w/fluiner 100 sx cement. to 3870'. F from 3747-51', 3754-58', 3761-63', & 2 868'. Its 15% NEA in 10 equal stages. Add block ter set at 3700' and place on injection.	dates, including estimated date of starting any proposed and loss additive. If necessary JSPI at 3786', 3812', 23', 30', sing material between stages. ief. January 12, 1972
	7. Describe Proposed or Complet work) SEE RULE 1103. Pull tubing w/ceme. Run tubing w/ceme. Squeeze open hole resqueeze w/anoth. Drill out cement. Perforate w/2 JSP 37', 42', 53' & 3 Acidize w/4000 ga. Run tubing w/pack	cker. ent retainer set at 3700'. e section w/100 sx. Class 'C' cement w/fluiner 100 sx cement. to 3870'. F from 3747-51', 3754-58', 3761-63', & 2 868'. Is 15% NEA in 10 equal stages. Add block the set at 3700' and place on injection. Asst. District Sup	dates, including estimated date of starting any proposed and loss additive. If necessary JSPI at 3786', 3812', 23', 30', sing material between stages. ief. January 12, 1972

RELILIVED

JAN 15 572

OIL CONSERVATION COMM.