NO. OF COPIES RECEIVED	1			Form C-103	
DISTRIBUTION	1	HUBBS	OFFICE	Supersedes Of 0. 0. 0. 0. 0. 0. 0. 0. 0. 0. 0. 0. 0.	ld 103
SANTA FE	NEW MEXICO OIL CONS	ERVATION COMMISSION	DIFTE	Effective 1-1-	65
FILE	1		IA	414 183	
u.s.g.s.	3 - NIMOCC	Jun 27	10 33	Indicate Type	of Lease
LAND OFFICE	1-File			State 🚤	Fee.
				5. State Oil & Ga	s Lease No.
OPERATOR	J				
24112	THE PERSON AND DEPOSIT OF	WELL C		mmm	
SUNDI (DO NOT USE THIS FORM FOR PR	RY NOTICES AND REPORTS ON OPOSALS TO DRILL OR TO DEEPEN OR PLUG BETON FOR PERMIT -" (FORM C-101) FOR SUC	WELLS ack to a different reservoir	₹.		
	TION FOR PERMIT - " (FORM C-101) FOR SUC	H PROPOSALS.)		7. Unit Agreemen	t Name
1. OIL GAS T				/. 0	
WELL WELL	OTHER-			0 57	News
2. Name of Operator				8. Farm or Lease	Mame
Tideweter	Oil Coopery			State	#T#
3. Address of Operator				9. Well No.	
P. O. Ben	249, Hobbs, Herr Mescleo (38840			2
4. Location of Well				10. Field and Po	ol, or Wildcat
•	- A4.	1090		Memme	m ė .
UNIT LETTER	1980 FEET FROM THESouth	LINE AND	FEET FROM	111111111	mmm
					
THE Westa LINE, SECT	10N16 TOWNSHIP 20=6	RANGE	NMPM.	HHHH	
				12, County	<i>HHHHH</i>
	15. Elevation (Show whether	DF, KI, GK, etc.)		12. County	
	3541 II	<u> </u>			<u> </u>
16. Check	Appropriate Box To Indicate N		rt or Otl	her Data	
	NTENTION TO:	-		REPORT OF:	
					 -
				ALTER	ING CASING
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK			ING CASING
	PLUG AND ABANDON	COMMENCE DRILLING OPNS.			AND ABANDONMENT
PERFORM REMEDIAL WORK	PLUG AND ABANDON		e		
PERFORM REMEDIAL WORK		COMMENCE DRILLING OPNS.	e		
PERFORM REMEDIAL WORK		COMMENCE DRILLING OPNS.	e .		
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER 17. Describe Proposed or Completed (COMMENCE DRILLING OPNS. LASING TEST AND CEMENT JO. OTHER		PLUG /	AND ABANDONMENT
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER 17. Describe Proposed or Completed (work) SEE RULE 1 103.	CHANGE PLANS CHANGE PLANS CHANGE PLANS	COMMENCE DRILLING OPNS. LASING TEST AND CEMENT JQ OTHER ails, and give pertinent dates		PLUG /	AND ABANDONMENT
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER 17. Describe Proposed or Completed (work) SEE RULE 1103.	CHANGE PLANS	COMMENCE DRILLING OPNS. LASING TEST AND CEMENT JQ OTHER ails, and give pertinent dates		PLUG /	AND ABANDONMENT
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER 17. Describe Proposed or Completed (work) SEE RULE 1 103.	CHANGE PLANS Department (Clearly state all pertinent det	COMMENCE DRILLING OPNS. CASING TEST AND CEMENT JO OTHER ails, and give pertinent dates	, including	PLUG /	AND ABANDONMENT
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER 17. Describe Proposed or Completed (work) SEE RULE 1 fo3.	CHANGE PLANS Department (Clearly state all pertinent det	COMMENCE DRILLING OPNS. LASING TEST AND CEMENT JQ OTHER ails, and give pertinent dates	, including	PLUG /	AND ABANDONMENT
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER 17. Describe Proposed or Completed (work) SEE RULE 1 fo3.	CHANGE PLANS Department (Clearly state all pertinent det	COMMENCE DRILLING OPNS. CASING TEST AND CEMENT JO OTHER ails, and give pertinent dates	, including	PLUG /	AND ABANDONMENT
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER 17. Describe Proposed or Completed (work) SEE RULE 1 103. Well shut in 1	Operations (Clearly state all pertinent det	COMMENCE DRILLING OPNS. LASING TEST AND CEMENT JO OTHER ails, and give pertinent dates CN STATUS THIS WELL.	, including	PLUG /	AND ABANDONMENT
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER 17. Describe Proposed or Completed (work) SEE RULE 1 103. Well shut in 1	Operations (Clearly state all pertinent det	COMMENCE DRILLING OPNS. LASING TEST AND CEMENT JO OTHER ails, and give pertinent dates CN STATUS THIS WELL.	, including	estimated date of	AND ABANDONMENT

CONDITIONS OF APPROVAL, IF ANY:

.9.2

TO HA EE UL SS HUL

All was Roll of the