N 'MEXICO OIL CONSERVATION (MMISSION

Santa Fe, New Mexico

MISCELLANEOUS NOTICES

Submit this notice in triplicate to the Oil Conservation Commission or its proper agent before the work specified is to begin. A copy will be returned to the sender on which will be given the approval, with any modifications considered advisable, or the rejection by the Commission or its agent, of the plan submitted. The plan as approved should be followed, and work should not begin until approval is obtained. See additional instructions in the Rules and Regulations of the Commission.

NOTICE OF INTENTION TO TEST CASING SHUT-OFF				NOTICE OF INTENTION TO SHOOT OR CHEMICALLY TREAT WELL		
NOTICE OF INTENTION TO CHANGE PLANS				NOTICE OF INTENTION TO PULL OR OTHERWISE ALTER CASING		
NOTICE OF INTENTION TO REPAIR WELL				NOTICE OF INTENTION TO PLUG WELL		
NOTICE C	OF INTENTION TO	DEEPEN WELI	L .			
		Mark 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1	Midland, Te	Piace	Kerch 17, 1937	e
OIL CON	SERVATION COMI	MISSION,				
	, New Mexico.					
Gentleme		ntiton to do o	ontoin work on d	lescribed below at th		
	FOLLOW		NS IN THE RULES		F WORK OF THE COMMISSION	
			SET CASING	AS PULLUMS:		
e vet	TOTAL CONTROL	awn m	TOTAL MITCHI	TOTAL DEPTH	NO SACKS & MAKE	FLUG CN
	CHT AMOUNT	SET AT	FORMATION	OF WELL	OF CEMENT	PLUC CN BCTTCM
	7; 3726 ·	3740 ·	FORMATION Lime	-		BOTTOM 5:00 F.
/2" 1	.7 _{ii} 3726 •	3740 *		OF WELL	OF CEMENT	BOTTOM 5:00 F
/2" 1	$7^{"}_{i}$ 3726 *	3740 *	Lime	<u>3745</u> •	OF CEMENT 100 Sacks El Toro	BOTTOM 5:00 F
/2" 1	$7^{"}_{i}$ 3726 *	3740 *	Lime	OF WELL	OF CEMENT 100 Sacks El Toro	BOTTOM 5:00 P
/2" 1	$7^{"}_{i}$ 3726 *	3740 *	Lime	<u>3745</u> •	OF CEMENT 100 Sacks El Toro	BOTTOM 5:00 F
/2" 1	$7^{"}_{i}$ 3726 *	3740 *	Lime	<u>3745</u> •	OF CEMENT 100 Sacks El Toro	BOTTOM 5:00 P
/2" 1 liburto:	$7^{"}_{i}$ 3726 *	3740 *	Lime	3745 •	OF CEMENT 100 Sacks El Toro arch 18, 1937.	BOTTOM 5:00 F. 3/16/37
/2" 1 liburto:	n method used with 1200% co.	3740 *	Lime	3745 •	OF CEMENT 100 Sacks El Toro arch 18, 1937.	BOTTOM 5:00 F. 3/16/37
/2" l liburto	n method used with 1200% co.	3740 *	Lime	3745 rill plug on Ma	OF CEMENT 100 Sacks El Toro arch 18, 1937. & Refining Company Company or Operator	BOTTOM 5:00 F. 3/16/37
/2" l liburto	n method used with 1200% co.	3740 *	Lime	OF WELL 3745 rill plug on Ma Humble Oil By PositionDivisi	OF CEMENT 100 Sacks El Toro arch 18, 1937. & Refining Company Company or Operator On Chief Clerk	BOTTOM 5:00 F. 3/16/37
/2" l liburto	n method used with 1200% co.	3740 *	Lime	OF WELL 3745 rill plug on Ma Humble Oil By PositionDivisi Send of	& Refining Company Company or Operator	BOTTCM 5:00 F. 3/16/37
/2" l liburto	n method used with 1200% co.	3740 ·	Lime	Till plug on Ma Humble Oil By Position Divisi Send of the Send	& Refining Company Company or Operator	BOTTCM 5:00 F. 3/16/37

11.10