

NEW MEXICO "F" STATE NO. 4 - CONTINUED

TIH w/4" perf. guns w/premium charges loaded 2 SPF & perf. Eumont Yates 7RQ Zone 5-1/2" csg. fr. 3542' - 3482' & fr. 3452' - 3387'. Acidize perfs. w/6300 gal. 15% NEFE DI HCL acid mixed w/70#/1000 gal. of acid of Sodium Erythorbate. Swab well. TIH w/pkr. set at +/- 3330'. Hydraulically frac. treat Eumont perfs. fr. 3387' - 3542' w/114,000 gal. of 60/55 constant internal phase quality foam & 310,000 lbs. of 12/20 Brady Sand. Flow back well. TIH w/prod. tbg. RU drlg. air eqpt. & clean out fill. Set tbg. O.E. at +/- 3464'. Remove BOP & install wellhead. RDPU, clean location & begin flowing well fr. Eumont Zone.