

N. M. CIV. CONS. COMMISSION
P. O. BOX 88240
HOBBS, NEW MEXICO
UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRI
(Other instruction
verse side)ATE
n reForm approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

LC-031621(b)

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Hobbs

9. WELL NO.

10. FIELD AND POOL, OR WILDCAT

Eunice-Monument GB/SA

11. SEC., T., R., M., OR BLM. AND
SURVEY OR AREA

18, T-20-S, R-37-E

12. COUNTY OR PARISH

Lea

13. STATE

New Mexico

SUNDRY NOTICES AND REPORTS ON WELLS
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

SEP 28 1981

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

Phillips Petroleum Company (663680)

3. ADDRESS OF OPERATOR

Room 401, 4001 Penbrook, Odessa, TX 79763

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

Unit K, 1980' from south and west lines

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3576' DF

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

☐
☐
☐
☐
☐

PULL OR ALTER CASING

☐
☐
☐
☐
☐

FRACTURE TREAT

MULTIPLE COMPLETE

SHOOT OR ACIDIZE

ABANDON*

REPAIR WELL

CHANGE PLANS

(Other)

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

☐
☐
☐
☒

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other) Perforate & Acidize

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

9-1-81: MI Tyler DD Unit pld rds & tbgs, instld BOP. Ran sd pmp to TD. GO ran GR/CNL caliper & CCL Logs from TD to 2000'. Perfd OH, w/Tornado frack jet shots, w/90 grams/shot from 3793'-3796', 3798'-3801', 3807'-3809', 3813'-3815', 3819'-3822', 3827'-3829', 3831'-3836', 3839'-3845', 3852'-3869', total of 43'--43 shots.

9-2-81: WIH w/2-7/8" tbgs & Baker Loc-Set pkr. Set pkr @ 3718'. Dresser/Titan trtd down 2-7/8" tbgs in OH 3778'-3870' w/5000 gals 15% NeFe Hcl. Flshd w/26 bbls 2% KCl wtr.

9-3-81: COOH w/tbgs & RTTS pkr. TIH w/2-7/8" tbgs, set DE @ 3850', SN @ 3850'.

9-4-81: Rng rods, SD 72 hrs.

9-8-81: Ran rods, set pmp @ 3830', pmpd 2" x 1-1/2" x 12', PD Tyler unit.

9-9-81: Pmpg, no gauge.

BOP Equip: Series 900, 3000#, double, w/1 set pipe rams and 1 set blind rams, manually operated.

(Cont'd on back)

18. I hereby certify that the foregoing is true and correct

SIGNED

W. J. Mueller

TITLE

Sr. Engineering Specialist

DATE 9-18-81

(This space for Federal or State office use)

APPROVED BY

TITLE

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side

ACCEPTED FOR RECORD

SEP 29 1981

U.S. GEOLOGICAL SURVEY
ROSWELL, NEW MEXICO

100-100000-100000

SEP 30 1988

GALEA 200000-100000
100-100000-100000
100-100000-100000
100-100000-100000
100-100000-100000