

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

OIL CONSERVATION DIVISION  
P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

WELL API NO.	30-025-06183
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.	B-160

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <del>X Shut-in</del>	7. Lease Name or Unit Agreement Name Eunice Monument Unit
2. Name of Operator Burgundy Oil & Gas of New Mexico, Inc.	8. Well No. 11
3. Address of Operator 401 W. Texas, Suite 1003, Midland, TX 79701-4413	9. Pool name or Wildcat Eunice Monument (GB-SA)
4. Well Location Unit Letter <u>E</u> : <u>2310</u> Feet From The <u>North</u> Line and <u>330</u> Feet From The <u>West</u> Line Section <u>19</u> Township <u>20S</u> Range <u>37E</u> NMPM Lea County	10. Elevation (Show whether DF, RKB, RT, GR, etc.)

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: _____ <input type="checkbox"/>		OTHER: <u>Temporary abandon</u> <input checked="" type="checkbox"/>	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. RUWL and mak JB run to 3620'
2. Set 7" CIBP @ 3600' - cap w/ 40' cmt - 5/6/97
3. Load csg w/ pkr fluid - 5/8/97
4. Run OCD MIT to 520# for 30" - ok - witnessed by Buddy Hill - 6/19/97

This Approval of Temporary Abandonment Expires 7-18-2008

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Ben Taylor TITLE Production Manager DATE 7/3/97  
 TYPE OR PRINT NAME Ben D. Taylor TELEPHONE NO. (915) 684-4033


(This space for State Use)

ORIGINAL SIGNED BY GARY WINK  
 FIELD REP. II TITLE \_\_\_\_\_ DATE \_\_\_\_\_

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_

JC96

dp



GRAPHIC CONTROLS CORPORATION  
BUFFALO, NEW YORK

BURGUNDY 0=1

EUNICE -  
MANHATTAN UNIT

6-19-97

BR 2221 B. H.

#11

E-19-20-37

SURF  
INT. - PUFF GAS.

30 MIN.

