

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

5a. Indicate Type of Lease
State ☒ Fee ☐

5. State Oil & Gas Lease No.

B-160

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator	Eunice Monument Unit
3. Address of Operator	8. Farm or Lease Name
P. O. Box 728, Hobbs, New Mexico 88240	Eunice Monument Unit
4. Location of Well	9. Well No.
UNIT LETTER K 1980 FEET FROM THE South LINE AND 1980 FEET FROM	26
THE West LINE, SECTION 20 TOWNSHIP 20-S RANGE 37-E NMPM.	10. Field and Pool, or Wildcat
	Eunice Monument-Grayburg San Andres
15. Elevation (Show whether DF, RT, GR, etc.)	12. County
3527' (DF)	Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input checked="" type="checkbox"/> Repair, Waterflow	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Rig up. Pull Rods and Pump. Install BOP. Pull tubing.
2. Set RBP @ 1320' and spot 2 sx sand on plug.
3. Perforate 5½" Casing W/2-JS @ 1232'.
4. Set Cement retainer @ 1150'. Cement to surface W/170 sx. Class h Cement containing 2% CaCl. WOC. DOC. Test.
5. Pull RBP.
6. Install pumping equipment. Test and return to production.

THE COMMISSION MUST BE NOTIFIED
24 HOURS PRIOR TO ANY WORK

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Jerry Sexton TITLE Asst. Dist. Mgr. DATE 8-3-83

ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT I SUPERVISOR

APPROVED BY _____ TITLE _____ DATE AUG 11 1983

CONDITIONS OF APPROVAL, IF ANY: