

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION  
P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-06200 ✓
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. B-2656
7. Lease Name or Unit Agreement Name State A-20
8. Well No. 1
9. Pool name or Wildcat Eumont (Yates-7Rvrs-Queen)
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3522'GR

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER
2. Name of Operator Meridian Oil Inc.
3. Address of Operator P.O. Box 51810, Midland, TX 79710-1810
4. Well Location Unit Letter I : 2310 Feet From The South Line and 330 Feet From The East Line Section 20 Township 20-S Range 37-E NMPM Lea County
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3522'GR

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: Add perfs and frac <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Run Epithermal Neutron log & GR/CCL. Pick perforating points. Perforations will be with 3 1/8" select fire casing gun. Perforate as directed. Breakdown perfs w/2500 gls of treated 2% KCl wtr & 7/8" RCMB. Fracture stimulate Penrose w/20,000 gls of 50-Quality CO2 foam & 60,000 lbs of 12/20 mesh Brady sand. Clean out with foam to PBTD. Put on Production.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Maria L. Perez TITLE Production Asst. DATE 7-18-91  
TYPE OR PRINT NAME Maria L. Perez TELEPHONE NO. 915-6865767

(This space for State Use)

APPROVED BY ORIGINAL SIGNED BY JERRY SEXTON TITLE DISTRICT I SUPERVISOR DATE JUL 22 1991  
CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

JUL 22 1991

926

MOBIL OFFICE