

NO. OF COPIES RECEIVED	
DISTRIBUTION	
ALTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

<p>SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG SITES TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT TO DRILL" (FORM C-101) FOR SUCH PROPOSALS.)</p>		<p>5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/></p>
<p>Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> OTHER <input type="checkbox"/></p>		<p>5. State Oil & Gas Lease No. B-2406</p>
<p>Name of Operator Atlantic Richfield Company</p>		<p>7. Unit Agreement Name</p>
<p>Address of Operator P. O. Box 1710, Hobbs, New Mexico 88240</p>		<p>8. Farm or Lease Name State 196</p>
<p>Location of Well UNIT LETTER L 990 FEET FROM THE South LINE AND 330 FEET FROM THE West LINE, SECTION 32 TOWNSHIP 20S RANGE 37E NMPM.</p>		<p>9. Well No. 12</p>
<p>10. Field and Pool, or Wildcat Eunice Monument Grbg SA</p>		
<p>11. Elevation (Show whether DF, RT, GR, etc.) 3546' GR</p>		<p>12. County Lea</p>

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data			
NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER Shut-in, hold for Waterflood <input checked="" type="checkbox"/>

1. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

On 8/25/76 was unable to pull open hole pkr from well in attempt to P&A. Left well tbg & pkr in hole & shut well in by flanging up wellhead & closing 2" gate valve on tbg. Holding well bore for possible use in secondary recovery at a later date.

Expire 10/1/76

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED	TITLE Dist. Drlg. Supv.	DATE 8/26/76
PROVED BY	TITLE	DATE
CONDITIONS OF APPROVAL, IF ANY:		

RECEIVED

1976

U.S. DEPARTMENT OF COMMERCE
WASHINGTON, D. C.