Submit 3 Copies To Appropriate District	State of]	New Me	exico		Form C-103
District I	Energy, Minerals and Natural Resources				Revised March 25, 1999
1625 N. French Dr., Hobbs, NM 88240				WELL API NO.	
<u>District II</u> 1301 W. Grand Ave., Artesia, NM 88210	OIL CONSERVATION DIVISION			30-025-00	5230
District III				5. Indicate Type	e of Lease
1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Francis Dr. Santa Fe, NM 87505			STATE	🔲 FEE X 🗌
<u>District IV</u> 1220 S. St. Francis Dr., Santa Fe, NM	Santa Fe	, NM 8	/505	6. State Oil &	Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS				7. Lease Name	or Unit Agreement Name:
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A]	e enter groement runne.	
PROPOSALS.)	DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH			Eumont Hard	y Unit
1. Type of Well:				Property No.	025104
Oil Well X Gas Well	Other				
2. Name of Operator				8. Well No.	
Permian Resources, Inc. OGRID No. 25797				9	
3. Address of Operator				9. Pool name or	Wildcat
P.O. Box 590 Midland, Texas 79701			1	-7Rvrs-Queen)Pool 22800	
4. Well Location			······	(22000
Unit LetterD:700	<u> feet from the </u>	Nor <u>th</u>	line and660_	feet from the	<u>West</u> line
Section 36	TT 11 AG	~ .	-		
Section 36	Township 200		Range 37E	NMPM	Lea County
	10. Elevation (Show w 3506' GL				
11. Check Ap	opropriate Box to Ind	licate N	ature of Notice,	Report or Other	r Data
NOTICE OF INT	ENTION TO:			SEQUENT RE	
PERFORM REMEDIAL WORK 🗌	PLUG AND ABANDON	⊡ xx	REMEDIAL WORK	< <u> </u>	
	CHANGE PLANS		COMMENCE DRI	LLING OPNS.	
	MULTIPLE	[]			ABANDONMENT // ///
	COMPLETION	1	CASING TEST AN		
			OFWENT JOD		
OTHER:			OTHER:		
12. Describe proposed or completed starting any proposed work). SEE	operations. (Clearly stat ERULE 1103 For Mult	e all perti inle Com	nent details, and giv	e pertinent dates,	including estimated date of
recompilation.			pietions. 2 titaen we	moore diagram or	proposed completion of
-					
Permian Resources, Inc. respectfi	ully submits the attached	plugging	procedure on the E	umont Hardy Unit	Well No. 9.

THE COMMESSION MUST BE NOTIFIED 24 HOURD PRIOR TO THE BEGINNING OF AUGCING OPERATIONS FOR THE C-103 TO BE APPROVED. $Q_{1}^{(1)}$

I hereby certify that the information abo	ye is true and comp	olete to the best	of my knowledge	and belief.		
SIGNATURE DALLARA Ma	tm T	ITLE <u>Regula</u>	tory Compliance		DATE_11-08- <u>02</u>	
Type or print name Barbara Watson		<u></u>		Telephone No.	915/685-0113	
(This space for State use)	$c \sim 10^{11} c \Lambda L$	SKA GET TU				
APPPROVED BY		TITLE	C. C. Marcikal		DATE	
Conditions of approval, if any:						



Permian Resources, Inc

Eumont Hardy No. 9

Eumont (Yates – 7Rvrs - Queen) Pool State Lease No. B-1130 API No. 30-025-06230

Surface Location 700' FNL & 660' FWL (Unit D) Section 36, T20S, R37E Lea County, New Mexico

DF 3506' GL

Spud Date4/17/54Completion Date 6/13/54Originally permitted and drilled by John M. Kelly as Tidewater State #1 Well

Existing Wellbore Condition	ons			
11-1/2" hole @ 1373'	8-5/8"	24 #/ft casing @ 3	1373'	Cmt'd w/ 200 sx. common TOC Unknown. Using gauge 11- 1/2" hole and 1.32 cuft/sx yield TOC calculates @ 536'.
8-1/4" hole @ 3598'	7"	23#/ft casing @ 3	3598'	Cmt'd w/ 200 sx. Total TOC Unknown. Using gauge 8- 1/4" hole and 1.32 cuft/sx yield TOC calculates @ 753'.
6-1/8" hole (assumed) @ 3683'	Open h	ole completion		
Completion			Natural COAF SITP 8 757#, 2 3 rd flow flow 24	tole 3598' – 3683' 1 IPf 1500 MCFPD 3200 MCFPD 05#, 1 st flow 24hrs 625 MCFPD FTP- 2 ^{pd} flow 24hrs 857 MCFPD FTP-701# v 24hrs 999 MCFPD FTP-675#, 4 th 4hrs 1437 MCFPD FTP-600#. eted in Eumont Gas Pool
		6/1/61	Contin	ental Oil Co. assumed operations
		6/1/67	Chang	e well name to Eumont Hardy #9
		12/30/61	3683' 3773'.	l to PBTD @ 3683'. DO CIBP(?) @ and drill 6-1/8" hole to new TD @ Ran GRNL. Ran 114 jts 2-3/8" cmt bg w/ PSA 3550'. Converted to
		9/23/76		NMOCD due to water flow problems ggs area.
		6/30/77	Well r	returned to WIW.

Permian Resources, Inc. Eumont Hardy No. 9 Proposed TA Procedure 11 November 2002 – Page 2

6/13/80	Ran MIT
2/9/81	Tbg or Pkr leak. Tbg parted. Fished tbg & pkr. RIH w/ 7" Model AD-1 + 114 jts 2- $3/8$ " IPC. PSA 3553'. Leak on csg-tbg annulus. SI.
8/1/83	Set 7" EZ drill CICR @ 3552'. Load csg w/ pkr fluid. Leak in retainer (small wtr flow). Replaced retainer and set 7" EZ drill CICR @ 3365'. Did not hold 600#. Dumped 3 sx cmt on top of retainer. Circ pkr fluid w/ no signs of fluid flow. Well TA'd. 8/4/83.
8/11/92	Ran bradenhead test, pressure to 500 #, bled down to 380 # in 30 mins. TA'd status approved ending 9/1/97.
8/26/94	Lynx request TA'd status. Approved by BLM for 12 mos, ending 9/27/95
10/23/01	RIH w/ tbg & pkr. Test for csg leaks. 7" csg tested good below 1542'. Found leaks from 1542 – 1507' w/ fluid flow in this interval. POOH w/ tbg & pkr. SI & WOO.

Proposed Plugging Procedure 11/5/02

- 1 Notify NMOCD Hobbs 24 hrs prior to MIRU.
- NDWH & dig out to surface csg valves. PU & RIH 2-3/8" workstring to top of CICR @
 3365'. RU cementer. Mix & spot 20 sx cmt on top of CICR from 3365 3300' (65' cmt).
 PUH to 3300' and circulate wellbore w/ 9.5 ppg mud laiden fluid.
- 3 POOH w/ tbg. RU wireline & RIH w/ strip gun. Perforate base of Salt @ 2550' w/ 2 sqz holes. RIH w/ pkr & tbg to 2550'. Mix & spot 40 sx plug from 2550' to 2313' (237' of cmt in 7", 23/ft csg). POOH w/ tbg to ± 2250' & set pkr. Attempt to sqz cement into perfs @ 2550'. Sqz & hold 500 psi. PUH w/ tbg to ± 1350', laying down balance.
- 4 RU wireline co and RIH w/ strip charge and shot 2 squeeze holes @ 1423' (50' below 8-5/8" / surface csg shoe w/ Anhydrite Top @ 1300'). RD wireline.
- 5 RIH w/ OE tbg to 1423' (50' below surface csg shoe). Mix & spot 40 sx plug from 1423' to 1186' (237' in 7" csg). PUH w/ tbg to ±1100' & NUWH. Attempt to squeeze cement into perfs @ 1423' and circulate up inside 7" x 8-5/8" annulus (open 7" x 8-5/8" surface csg valve and note flow). Displace plug to no lower than 1275'. SI & WOC. RIH & tag cmt top at no lower than 1323'.
- 6 POOH w/ tbg. RU wireline co and RIH w/ strip charge and shot 2 deep penetrating squeeze holes through both 7" and 8-5/8" casing @ 500". RD wireline. NUWH and pump down 7" csg to see if circulation out 7" x 8-5/8" annulus and / or between 8-5/8" x 11-1/2" surface hole. If circulation, RU cementer and mix & pump 200 sx down 7" csg and circulate to

Permian Resources, Inc. Eumont Hardy No. 9 Proposed TA Procedure 11 November 2002 – Page 3

surface through both 7" x 8-5/8" annulus and 8-5/8" x 11-1/2" annulus. Displace plug to no lower than 350'. SI & WOC.

- 7 Mix & spot 10 sx plug from ± 50' to surface inside 7" surface csg. POOH w/ tbg and lay down.
- 8 RD WSU & cementer. Clean location & pits. Weld on P&A marker. File final NMOCD Form 103 P&A report.