

NEW MEXICO OIL CONSERVATION COMMISSION

Santa, Fe, New Mexico

MISCELLANEOUS NOTICES

Submit this notice in triplicate to the Oil Conservation Commission or its proper agent before the work specified is to begin. A copy will be returned to the sender on which will be given the approval, with any modifications considered advisable, or the rejection by the Commission or agent, of the plan submitted. The plan as approved should be followed, and work should not begin until approval is obtained. See additional instructions in the Rules and Regulations of the Commission.

Indicate nature of notice by checking below:

NOTICE OF INTENTION TO TEST CASING SHUT-OFF	NOTICE OF INTENTION TO SHOOT OR CHEMICALLY TREAT WELL	
NOTICE OF INTENTION TO CHANGE PLANS	NOTICE OF INTENTION TO PULL OR OTHERWISE ALTER CASING	
NOTICE OF INTENTION TO REPAIR WELL	NOTICE OF INTENTION TO PLUG WELL	X
NOTICE OF INTENTION TO DEEPEN WELL		

Hobbs, New Mexico

Place

Mar. 14, 1939

Date

OIL CONSERVATION COMMISSION,
Santa Fe, New Mexico.Note- Will notify Oil Conservation Commission
by phone when work is started.

Gentlemen:

Following is a notice of intention to do certain work as described below at the

Repollo Oil Company

Company or Operator

W. C. Roach

Lesse

Well No. 4 in N.W.S.W.of Sec. 21, T. 20S, R. 37E, N. M. P. M., Eunice Field,
Lea County.

FULL DETAILS OF PROPOSED PLAN OF WORK

FOLLOW INSTRUCTIONS IN THE RULES AND REGULATIONS OF THE COMMISSION

Total Depth- 3875' - Reason for plugging- Very small show oil after shooting and acidizing and an unexhaustible amount of sulphur water. The well now has a cement plug from 3875 to 3860'. Propose to cement from 3860 to well up into 7"OD Casing which is set @ 3636'. After cement sets will fill 7"OD casing with heavy mud to approximately 2200' and then knock off 7"OD casing at Approx. 2200'. Set cement plug at point 7"OD Casing is knocked off, after setting cement plug will run heavy mud in 7"OD casing sufficient to fill hole to approximately 300' from the top then pull the 7"OD Casing adding mud as necessary to keep top within 300' of top of hole. Then knock off the 9 5/8"OD casing at approximately 300' from the top. 9 5/8"OD casing set @ 1205'. After knocking off 9 5/8"OD casing will set cement plug at point knocked off, allow to set and fill 9 5/8"OD casing with heavy mud and then pull casing. The 13"OD Casing set @ 220' will stay in hole as it is cemented to surface. Will fill 13"OD casing with heavy mud to bottom of cellar. Will cement a piece of 4" pipe of sufficient length, in top of 13"OD casing, to extend 4' above the ground level, as the regulation "MARKER". After "Marker" is cemented will fill cellar level with surface.

Approved _____, 19_____
except as follows:Repollo Oil Company

Company or Operator

By L. SurrattPosition Dist. Supt.

Send communications regarding well to

Name L. Surratt,Address Hobbs, N.M.

OIL CONSERVATION COMMISSION,

By R. O. GarbroughTitle OIL & GAS INSPECTOR

DUPLICATE