Form 9-331 a (March 1942)

## (SUBMIT IN TRIPLICATE)

## Lease No. A. 031620 (a) Unit N. V. F. U.

Title Asst, District Superistendent

## UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

## SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING SUBSEQUENT REPORT OF ALTERING CASING SUBSEQUENT REPORT OF REDRILLING OR REPAIR
NOTICE OF INTENTION TO PULL OR ALTER CASING	
(INDICATE ABOVE BY CHECK MARK	Hobbs New Marcles hierestay 28 , 19 50
	om S line and wooft. from E line of sec. 24.
SE/L Sec. 24         20         3           (4 Sec. and Sec. No.)         (Twp.)           Skuggs         Interpretation (County County	(Range) (Meridian)  Or Subdivision) (State or Territory)
The elevation of the derrick floor above sea le	
(State names of and expected depths to objective sands: show size	ILS OF WORK  res, weights, and lengths of proposed casings; indicate mudding jobs, cement- other important proposed work)
Set /* casing at 3699 and depth of hole 3700 in line. Flug behind ending 400 by Temperature 3	camented with 1725 sacks coment. Total down at 2:20 P.W. 10-30-50. Top of cament urvey.
Final presence 1180%. Found top of	ted closing with 1200% for 30 minutes.  cement plug at 3640. Drilled out cement h 1200% for 30 minutes. Plus preseure
	<u>-</u>
I understand that this plan of work must receive approval in	writing by the Geological Survey before operations may be commenced.
Company Continent 1 011 Company	
Address CC	3
liebbe, Net Food co	By Docolin

U. S. SOVERNMENT PRINTING OFFICE 18-8437-3

A Section of the Sect Brigger of the State of the Control 다. 설 동안 보다 그 것 같 . 3€ i di ilgani di 🕏 at we **34** 3 The state of the s

the state of the contract of

5°\$ , ≰÷

#31 ±4. B¥ (\$ 3 € °

The second of the second second second