

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT
P.O. BOX 1980
HOTEL NEW MEXICO

Budget Bureau No. 1004-0135
Expires August 31, 1985
5. LEASE DESIGNATION AND SERIAL NO.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐	7. UNIT AGREEMENT NAME
2. NAME OF OPERATOR Conoco Inc.	8. FARM OR LEASE NAME Semu Meyer Blinbury
3. ADDRESS OF OPERATOR P.O. Box 460 - Hobbs NM 88240	9. WELL NO. 82
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 1980' FSN & 990' FEN Unit I	10. FIELD AND POOL, OR WILDCAT Blinbury Oil & Gas
14. PERMIT NO. 30-025-06261	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA 25-20S-37E
15. ELEVATIONS (Show whether DP, RT, GR, etc.)	12. COUNTY OR PARISH Lea
	13. STATE NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF	☐	PULL OR ALTER CASING	☐
FRACTURE TREAT	☐	MULTIPLE COMPLETE	☐
SHOOT OR ACIDIZE	☐	ABANDON*	☐
REPAIR WELL	☐	CHANGE PLANS	☐
(Other)	☐		☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF	☐	REPAIRING WELL	☐
FRACTURE TREATMENT	☐	ALTERING CASING	☐
SHOOTING OR ACIDIZING	☐	ABANDONMENT*	☒
(Other)	☐		☐

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

Work started on 1/27/87 and completed 1/30/87. POOH w/ prod equipment. Run scraper to 5801' & POOH. Set CIBP at 5735'. Spot 5 sxs cmt on top of CIBP at 5735'. Spot 65 sxs cmt from 4091' - 2504'. Run scraper to 1400' & POOH. Perf at 1350' w/ 4" spf. Runable to pump into perf. Perf at 1320' & 1300' w/ 4" spf. Spot 250 gal 15% HCL-NE-FE acid across perfs. Set retainer at 1242'. Squeeze top of salt section w/ 500 sxs of class "C" neat cmt. Spot 80' of cmt on top of retainer. Spot 33 sxs class "C" cmt w/ 4% CaCl₂ from 408' - 308'. WOC. Tag cmt at 310'. Spot 20 sxs class "C" cmt w/ 4% CaCl₂ from 60' to surface. Rmpd 50 sxs class "C" neat between 9 7/8" & 13 7/8" csg. Remove wellhead and install P&M marker.

18. I hereby certify that the foregoing is true and correct

Operator

TITLE _____

DATE April 14, 1987

(For use by Bureau or State office use)

Bureau or State Office Use

TITLE _____

DATE 4-24-87

REMARKS OF APPROVAL, IF ANY:

*See instructions on Reverse Side

Section 101 of the Federal Criminal Code makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

JBHM-Cadspad(6) ARCC(2) AMCC(2) CHEVRON(1) FILE

E