

Submit 3 Copies To Appropriate District Office

District I

1625 N. French Dr., Hobbs, NM 88240

District II

1301 W. Grand Avenue, Artesia, NM 88210

District III

1000 Rio Brazos Rd., Aztec, NM 87410

District IV

1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-103
Revised March 25, 1999

WELL API NO.
30-025-06281

5. Indicate Type of Lease

STATE ☒ FEE ☐

6. State Oil & Gas Lease No.

7. Lease Name or Unit Agreement Name:

Eunice Monument South Unit

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

Oil Well ☒ Gas Well ☐ Other ☐

2. Name of Operator Chevron USA, INC

8. Well No.
113

3. Address of Operator 15 Smith Rd, Midland, Tx 79704

9. Pool name or Wildcat
Eunice Monument GRAYBURG S.A.

4. Well Location

Unit Letter H : 1980 feet from the North line and 660 feet from the East line

Section 30 Township 20-S Range 37E NMPM County Lea

10. Elevation (Show whether DR, RKB, RT, GR, etc.)

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐ CHANGE PLANS ☐

PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☒

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.

1. SET CIBP @ 3640' MIX & PUMP 80SX PLUG FR/3640' TO 3200' (SAN ANDRES, QUEENS) TAG @ 3120'
2. DISPLACE HOLE W/MLF, 9.5# BRINE W/25# GEL P/BBL
3. PERF 4 HOLES @ 2600' SQZ W/75SX FR/2600' TO 2450' (8 5/8" SHOE, B-SALT) TAG @ 2356'
4. PERF 4 HOLES @ 1100' SQZ W/50SX FR/ 1100' TO 1000' (T-SALT) TAG @ 957'
5. PERF 4 HOLES @ 251' SQZ W/100SX FR/ 251' TO 150' (12 1/2" SHOE) TAG @ 29'
6. TOP OF WELL W/CMT FR/29' TO SURF, INSTALL DRY HOLE MARKER

Compl 6-13-02

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Jimmy Bagley TITLE PRESIDENT Sunset Sew DATE 6-21-02

Type or print name JIMMY BAGLEY

(This space for State use)

Telephone No. 915 520-8756

APPROVED BY [Signature] TITLE Fed Rep DATE 7-4-03

Conditions of approval, if any:

GWW