STATE OF NEW MEXICO NERGY AND MINERALS DEPARTMENT

C. ~	
1	
	1
_	
1	i
\vdash	-

OIL CONSERVATION DIVISION

SUNDRY NOTICES (00 NOT USE THIS FORM FOR PROFOSALS TO DHII USE "APPLICATION FOR PERMIT	P. O. BO SANTA FE, NEV	ATION DIVISION DX 2088 V MEXICO 87501	Form C-103 Revised 10-1 Sa. Indicate Type of Lease State X Fee S. State Oil 6 Gas Lease No.
FILE U.S.G.S. LAND OFFICE OPERATUR SUNDRY NOTICES (DO NOT USE THIS FORM FOR PROFISALS TO DHII USE "APPLICATION FOR PERMIT	SANTA FE, NEV	V MEXICO 87501	Revised 10-1 Sa. Indicate Type of Lease State X Fee
U.S.G.S. LAND OFFICE OPERATUR SUNDRY NOTICES (DO NOT USE THIS FORM FOR PROFOSALS TO DHI) USE "APPLICATION FOR PERMIT			Sa. Indicate Type of Lerise State X Fee
SUNDRY NOTICES SUNDRY NOTICES (DO NOT USE THIS FORM FOR PROFOSALS TO DHII USE "APPLICATION FOR PERMIT	AND REPORTS ON		State X Fee
SUNDRY NOTICES (DO NOT USE THIS FORM FOR PROPOSALS TO DHII USE "APPLICATION FOR PERMIT	AND REPORTS ON		State X Fee
SUNDRY NOTICES (DO NOT USE THIS FORM FOR PROPOSALS TO DHII USE "APPLICATION FOR PERMIT	AND REPORTS ON		
	AND REPORTS ON		5. State Oil & Gas Leaso No.
	AND REPORTS ON		
		WELLS	
	- (FORM C-151) FCR 50	CH PROPOSALS.	
WELL EX WELL OTHER.		7. Unit Agreement Name	
ame at Cperator		Eunice Monument South	
Chevron U.S.A. Inc.		8. Farm or Lease Name	
ddress of Operator			
P.O. Box 670, Hobbs, NM 88240			9. Well No.
Location of Wall		110	
• • •			10. Field and Pool, or Wildcat
HIT LETTER E . 1980 FEET FROM THE NORTH LINE AND 660 FEET FROM		To reid and post, or widget	
		Eunice Monument G/SA	
THE West LINE, SECTION 30	200	275	
	TOWNSHIP	RANGE NA	
MINITED TO SECTION OF THE PARTY	Flexation (Show what	DC DT CD	<u> </u>
15. Elevation (Show whether DF, RT, GR, etc.)		12. County	
Manual Company	3533		Lea
Check Appropriate	Box To Indicate N	ature of Notice, Report or	0.1 2
NOTICE OF INTENTION T	·o:	support of	other Data
		20825005	ENT REPORT OF:
ORM PEMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	
PORAPILY ABANDON		L	ALTERING CASING
OR ALTER CASING	CHANGE PLANS	COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT
	CHANGE PLANS	ADE THEMES ON TEST BHILLS	_
Ther_		other don, log, perf a	cdz.
escribe Proposed or Completed Operations (Classic	w state all		
escribe Proposed or Completed Operations (Clearly ork) SEE RULE 1103.	, socialis pertinent deta	its, and give pertinent dates, includ	ing estimated date of starting any proposi-

Cleaned out from 3806' to 3820'. Drilling f/3820' to 3958'. Circulate, run CNL,GR,CCL, perf w/ 4" guns 1 JHPF, 180° phased, 7 holes in zone 1 at 3682' to 3688'. Spot 100bbls 15% NEFE HCL f/3688 to 3605. Acidize new and old perf interval in zone 1 at 3625 to 3688 w/2400 gallons 15% NEFE HCL. Swab. TIH w/2 3/8" production tubing (Est top 3934'). Run pmp and rods, Test to 500psi, ok. Turned over to production. Work performed 9-5/87 through 9/9/87.

I hereby certify that the information above is true and comple	te to the best of my knowledge and belief.		
m. E. apin	Staff Drilling Engineer	DATE	September 11, 198
ORIGINAL SIGNED BY JERRY SEXTON DISTRICT I SUPERVISOR HOLLIONS OF APPROVAL, IF ANY:	TITLE	DATE	SEP 1.5 1987