

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	D 3423
7. Unit Agreement No.	
8. Farm or Lease Name	
9. Well No.	4
10. Field and Pool, or Wildcat	Bunice-Monument (G-SA)
12. County	Lea

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR NOTICES TO DRILL OR TO DEEPEN OR PULL BACK TO A DIFFERENT RESERVOIR. SEE MAPS, CATALOGS, PERMIT FORMS, CATALOGS FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>
2. Name of Operator Amerasia Hess Corporation
3. Address of Operator Drawer "D", Monument, New Mexico 88265
4. Location of Well UNIT LETTER <u>E</u> <u>1980</u> FEET FROM THE <u>North</u> LINE AND <u>660</u> FEET FROM THE <u>East</u> LINE, SECTION <u>30</u> TOWNSHIP <u>20-S</u> RANGE <u>37-E</u> N.M.P.M.
15. Elevation (Show whether DF, RT, GR, etc.)

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input checked="" type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Plan to: Plug back from Grayburg-San Andres oil section with bridge plug and cement. Perforate G-SA gas interval as per logs. Treat perforations with 15% HF acid. Swab test. Run production equipment resume production as a gas well in oil reservoir.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED MPB TITLE Supvr., Admin. Services DATE 9-16-75
APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY: _____