

N.

## NEW MEXICO OIL CONSERVATION COMMISSION

Santa Fe, New Mexico

## WELL RECORD

Mail to Oil Conservation Commission, Santa Fe, New Mexico, or its proper agent not more than twenty days after completion of well. Follow instructions in the Rules and Regulations of the Commission. Indicate questionable data by following it with (?). SUBMIT IN TRIPLICATE.

AREA 640 ACRES  
LOCATE WELL CORRECTLY

Company or Operator

Address

Well No.

in

of Sec.

T.

Lease

R. M. P. M.

Field

County

Well is

feet south of the North line and

feet west of the East line of

If State land the oil and gas lease is No.

Assignment No.

If patented land the owner is

Address

If Government land the permittee is

Address

The Lessee is

Address

Drilling commenced

Drilling was completed

Name of drilling contractor

Address

Elevation above sea level at top of casing

The information given is to be kept confidential until

19

## OIL SANDS OR ZONES

No. 1, from

to

No. 4, from

to

No. 2, from

to

No. 5, from

to

No. 3, from

to

No. 6, from

to

## IMPORTANT WATER SANDS

Include data on rate of water inflow and elevation to which water rose in hole.

No. 1, from

to

feet.

No. 2, from

to

feet.

No. 3, from

to

feet.

No. 4, from

to

feet.

## CASING RECORD

SIZE	WEIGHT PER FOOT	THREADS PER INCH	MAKE	AMOUNT	KIND OF SHOE	CUT & FILLED FROM	PERFORATED FROM	TO	PURPOSE
10-1/4"	32.75	11		122'	API				
7-1/2"	28.40	11		122'	API				
5-1/2"	17	11		122'	API				

## MUDDING AND CEMENTING RECORD

SIZE OF HOLE	SIZE OF CASING	WHERE SET	NO. SACKS OF CEMENT	METHOD USED	MUD GRAVITY	AMOUNT OF MUD USED
10-1/4"	12-1/4"	11'	100	dry mix	10.0	400 gal.
7-1/2"	8-1/2"	11-30'	400	dry mix	10.0	1600 gal.
5-1/2"	6-1/2"	11-30'	100	dry mix	10.0	400 gal.

## PLUGS AND ADAPTERS

Heaving plug—Material

Length

Depth Set

Adapters—Material

Size

## RECORD OF SHOOTING OR CHEMICAL TREATMENT

SIZE	SHELL USED	EXPLOSIVE OR CHEMICAL USED	QUANTITY	DATE	DEPTH SHOT OR TREATED	DEPTH CLEANED OUT

Results of shooting or chemical treatment

## RECORD OF DRILL-STEM AND SPECIAL TESTS

If drill-stem or other special tests or deviation surveys were made, submit report on separate sheet and attach hereto.

## TOOLS USED

Rotary tools were used from

feet to

feet, and from

feet to

feet

Cable tools were used from

feet to

feet, and from

feet to

feet

## PRODUCTION

Put to producing

xxx 16,

19

The production of the first 24 hours was

barrels of fluid of which

% was oil;

% emulsion;

% water; and

% sediment. Gravity, Be

If gas well, cu. ft. per 24 hours

Gallons gasoline per 1,000 cu. ft. of gas

Rock pressure, lbs. per sq. in.

## EMPLOYEES

Driller

Driller

Driller

Driller

## FORMATION RECORD ON OTHER SIDE

I hereby swear or affirm that the information given herewith is a complete and correct record of the well and all work done on it so far as can be determined from available records.

Subscribed and sworn to before me this

10th

day of

November

1936

Place

Date

Name

Position

Representing

Company or Operator

My Commission expires

## FORMATION RECORD

FROM	TO	THICKNESS IN FEET	FORMATION
10	10	0	11107
11	10	0	11107
12	110	0	11107
13	110	0	11107
14	110	0	11107
15	110	0	11107
16	110	0	11107
17	110	0	11107
18	110	0	11107
19	110	0	11107
20	110	0	11107
21	110	0	11107
22	110	0	11107
23	110	0	11107
24	110	0	11107
25	110	0	11107
26	110	0	11107
27	110	0	11107
28	110	0	11107
29	110	0	11107
30	110	0	11107
31	110	0	11107
32	110	0	11107
33	110	0	11107
34	110	0	11107
35	110	0	11107
36	110	0	11107
37	110	0	11107
38	110	0	11107
39	110	0	11107
40	110	0	11107
41	110	0	11107
42	110	0	11107
43	110	0	11107
44	110	0	11107
45	110	0	11107
46	110	0	11107
47	110	0	11107
48	110	0	11107
49	110	0	11107
50	110	0	11107
51	110	0	11107
52	110	0	11107
53	110	0	11107
54	110	0	11107
55	110	0	11107
56	110	0	11107
57	110	0	11107
58	110	0	11107
59	110	0	11107
60	110	0	11107
61	110	0	11107
62	110	0	11107
63	110	0	11107
64	110	0	11107
65	110	0	11107
66	110	0	11107
67	110	0	11107
68	110	0	11107
69	110	0	11107
70	110	0	11107
71	110	0	11107
72	110	0	11107
73	110	0	11107
74	110	0	11107
75	110	0	11107
76	110	0	11107
77	110	0	11107
78	110	0	11107
79	110	0	11107
80	110	0	11107
81	110	0	11107
82	110	0	11107
83	110	0	11107
84	110	0	11107
85	110	0	11107
86	110	0	11107
87	110	0	11107
88	110	0	11107
89	110	0	11107
90	110	0	11107
91	110	0	11107
92	110	0	11107
93	110	0	11107
94	110	0	11107
95	110	0	11107
96	110	0	11107
97	110	0	11107
98	110	0	11107
99	110	0	11107
100	110	0	11107