

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

SEP 22 1966

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>

5. State Oil & Gas Lease No.

**B-1167**

## SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator <b>Shell Oil Company (Western Division)</b>	8. Farm or Lease Name <b>State J</b>
3. Address of Operator <b>P. O. Box 1509, Midland, Texas 79701</b>	9. Well No. <b>2</b>
4. Location of Well UNIT LETTER <b>0</b> , <b>660</b> FEET FROM THE <b>south</b> LINE AND <b>1980</b> FEET FROM THE <b>east</b> LINE, SECTION <b>32</b> TOWNSHIP <b>20S</b> RANGE <b>37E</b> NMPM.	10. Field and Pool, or Wildcat <b>Eunice</b>
15. Elevation (Show whether DF, RT, GR, etc.) <b>3541' DF</b>	12. County <b>Lea</b>

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK	<input checked="" type="checkbox"/>
TEMPORARILY ABANDON	<input type="checkbox"/>
PULL OR ALTER CASING	<input type="checkbox"/>
OTHER	<input type="checkbox"/>

PLUG AND ABANDON ☐

CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐

COMMENCE DRILLING OPNS. ☐

CASING TEST AND CEMENT JOB ☐

OTHER ☐

ALTERING CASING ☐

PLUG AND ABANDONMENT ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Pull rods, pump, and tubing.
2. Run 1-300 grns/ft. and 1-500 grns/ft. string shot over open hole interval 3700'-3800'.
3. Treat with 2000 gal. 28% NEA, followed with 2000 gal. fresh water, and 1200 gal. lease crude.
4. Recover load.
5. Run production equipment.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

Original Signed By  
N. W. Harrison

SIGNED **N. W. Harrison**

TITLE **Senior Exploitation Engineer**

DATE **September 22, 1966**

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY: