

JAL OIL COMPANY - SARKEYS NO. 2 - SECTION 25-T21S-R37E

AUGUST 27, 1957 C-101 and C-128 filed.

AUGUST 28, 1957 C-101 and C-128 approved.

SEPTEMBER 5, 1957 C-103 filed. Results of Casing Shut-off Test. 9-5/8" csg. 1172'. Cement circulated. Test to 500 psig. No leak. Work performed September 1, 1957. C-103 approved this date.

OCTOBER 10, 1957 C-102 filed. Notice of Intention to Change Plans & Intention to Set Liner. Proposed to run 7" csg. at 5797' and cement with 600 sax at shoe and 200 sax at 2 stage. Tool set at 1288'. 5" extreme line liner to be run and cemented to top of Tubb pay.

OCTOBER 11, 1957 C-102 approved except as follows: "that cement behind 5" liner must be tied into the 7"."

OCTOBER 14, 1957 Received application for permit to dually complete as oil well in Tubb and Blinbry zones. Also sketch showing mechanical completion. C-128 filed. Plat showing well location & offset owners.

OCTOBER 16, 1957 C-103 filed. Results of Casing Shut-off Test. 7" csg. set at 5800'. Cemented with 600 sax below DV Tool. Test to 1000# for 30 min. OK. Work performed October 9, 1957. C-103 approved this date.

OCTOBER 23, 1957 C-103 filed. Setting 5" Liner & Results of Casing Shut-off Test. 5" O.D. 17.93# SMLS Liner Casing J-55 Range 2 Liner. Hanger set at 5785', Shoe at 6335'. Cemented with 50 sax, reversed out approx. 10 sax. Test to 1500# for 30 min. OK. C-103 was approved, but showed no date.

OCTOBER 31, 1957 Form C-110 filed. Using same tank battery as R. Olsen Sarkeys No. 1. C-110 approved this date.

C-104 filed. Request for oil allowable - Tubb Pool. Perfs. 6180-6315' - 4 shots/foot. Tr. with 500 gal. mud acid, 9000 gal. 15% acid. Tubing Press. 225#. IP: 52 BOPD - Choke size 3/4". C-104 approved this date.

C-105 filed. Drilling started 8/30/57 - Completed 10/18/57. Gravity 47.1 degrees. Top pay 6180' Tubb zone.

NOVEMBER 1, 1957 Received amended application for permit to dually complete as oil well in Tubb & Blinbry zones. Dual completion data filed.

NOVEMBER 4, 1957 C-103 filed. To correct gravity from 47.1 degrees to 44.1 degrees. C-103 approved this date.

DECEMBER 13, 1957 C-102 filed. Notice of Intention to Gun Perforate, Acidize, and Frac. Proposed to perforate Blinbry 5570' to 5769'. Acidize with 100 gal. mud acid - clean up. Acidize with 3000 gal. 15% acid - clean up and test. Sand frac with 20,000 gal. oil & 20,000# sand if necessary.

DECEMBER 13, 1957
(continued)

(On this Form C-102 a request for emergency allowable was made to be set up for testing after treatment. This request was marked out with ink line, but it is unknown whether by R. Olsen or OCC.)
Form C-102 approved this date.

JANUARY 27, 1958

C-110 filed. Notification of change in ownership from R. Olsen to Jal Oil Company, Inc. effective January 1, 1958.

JANUARY 30, 1958

C-103 filed. Notification of change of ownership from R. Olsen to Jal Oil Company, Inc. effective January 1, 1958.
This C-103 was approved July 22, 1958.

FEBRUARY 11, 1958

C-110 filed January 27, 1958 was approved this date.

MARCH 13, 1958

C-110 filed. Allowable of 1000 bbls. requested for month of March for testing purposes.
C-110 approved this date.

MAY 19, 1958

Received letter from W. D. Girard, lawyer for Jal Oil Company, with amended application brief and request for this application to be set up for examiners hearing.

AUGUST 25, 1958

C-110 filed. Well completed under Dual Order No. R-1217.
C-110 approved this date.

C-104 filed. Completed in Elinebry under Dual Order No. R-1217. Perfs. 5570' to 5769'. A/w 7500 15% SLT and 1000 gals. mud acid. IP: 40 BOPD. 3/4" choke.
Notation: "A testing allowable was issued on this well and 2100 bbls. oil produced."
C-104 approved this date.

Letter from OCC stating that within 15 days it would be necessary to submit all forms which had not previously been submitted as required by Order R-1217.

SEPTEMBER 6, 1958

Exhibits "3" and "5" with draft of Dual Tubing Suspension Assembly filed.

SEPTEMBER 23, 1958

Packer Leakage Test filed.
Elinebry Test 2/14/58.
Oil flow rate during test: 55.68 BOPD based on 37.12 BO in 16 hrs.
Gas flow rate during test: 292,693 MCFPD based on 195,226 MCF in 16 hrs.
Tubb Test 2/16/58.
Oil flow rate during test: 316.8 BOPD based on 33 BO in 2.5 hrs.
Gas flow rate during test: 592,232 MCFPD based on 61,690 MCF in 2.5 hrs.
Remarks: "Tubb was flowed 2.5 hrs. because recent test well flowed until it died; well wouldn't kick off and flow again because of test. Well normally flowed on Intermittent, 16 min. on & 160 min. off."

SEPTEMBER 29, 1959

Packer Leakage Test filed.
Elinebry Test 6/22/59.
Oil production during Test: 4.1 bbls. in 3 hrs.
Gravity 43.7.
Gas production during test: 39.8 MCF in 3 hrs.
GOR - 9,710.

qidatentwo tot Jeasper a 501-C moit acht no)
gyl qu jee ed et abm aw sidewallin
beriam aw Jeasper sidi. Tiel
tefiai aw swormik et si aw enti. and
.000 no neal 0.8
.esab acht bevorqqa 501-C moit

DECEMBER 13, 1952
(cont'd)

qidatentwo ni egndi to notificatiom .belit OII-C
et aw Jeasper a 501-C moit
.8281 , 1 , 1952

8281 , 25 YIAUKAL

qidatentwo to egndi to notificatiom .belit 501-C
et aw Jeasper a 501-C moit
.8281 , 1 , 1952
.8281 , 25 yiaukal bevorqqa aw 501-C acht

8281 , 30 YIAUKAL

tot Jeasper .tot 0001 to sidewallin ,belit OII-C
bonyt tot Jeasper qmbocey
.8281 , 1 , 1952

8281 , 31 YIAUKAL

tot Jeasper ,tunek ,tunek tot 1st
bonyt tot Jeasper bebaam achi ,tunek
tot qu jee ed et notificatiom acht tot Jeasper
.8281 , 1 , 1952

8281 , 31 HOMAN

tot 0001 aw tenek bonyt 0101
.8281 , 1 , 1952
.esab acht bevorqqa 501-C

8281 , 31 YAM

tot 0101 aw tenek bonyt 0101
tot 0001 aw tenek bonyt 0101
aw 0101 aw 0101 aw 0101 aw 0101 aw 0101 aw
".beoubong llo .afdd 001S bns llow
.esab acht bevorqqa 501-C

8281 , 32 YIAUKAL

ji ayab 21 minik jaae qmbocey 000 moit tenek
bad dolik amic illa jiaukal aw qmbocey ed blin
yt berklper es bejklper need ylauclveriq Jan
.7551-B rebrQ

8281 , 33 HEMETTA

gimduf land to jiaukal dulu "E" bns "C" awidik
.belit qidatentwo notificatiom

8281 , 33 KIYIMPA

.belit jaae qmbocey tenek
.8281 , 33 Jee tenek

no beasd 0908 88.22 :jeet ylauclveriq aw 110
.aw 31 at 06 51.3

beasd 0908N 88.22 :jeet ylauclveriq aw 110
.aw 31 at 06 52.281 no

.8281 , 33 Jee tenek
no beasd 0908 8.812 :jeet ylauclveriq aw 110
.aw 3.2 at 06 51

beasd 0908N 88.22 :jeet ylauclveriq aw 110
.aw 3.2 at 06 52.281 no

ji ayab 21 minik jaae qmbocey 000 moit tenek
bad dolik amic illa jiaukal aw qmbocey ed blin
yt berklper es bejklper need ylauclveriq Jan
.lllo .afdd 001 A no .nim 21 ,rejklper no beasd

8281 , 35 KIYIMPA

.belit jaae qmbocey tenek
.8281 , 35 Jee tenek

.aw 3 at .afdd 1.4 :jeet ylauclveriq aw 110
.aw 3.4 at 06 52.281 no

.aw 3 at 06 52.281 :jeet ylauclveriq aw 110
.0111 , P - HOD

-3-

Sarkeys No. 2

SEPTEMBER 29, 1959

Tubb Test 6/23/59
Oil production during test: 5.2 bbls. in 3 hrs.
Gravity 43.3 degrees.
Gas Production during test: 153.9 MCF in 3 hrs.
GOR - 29,700.

OCTOBER 8, 1959

Packer Leakage Test approved this date.

FEBRUARY 12, 1960

C-103 filed. Perforating & Acidizing Blinbry Zone.
Perfs. 5560' to 5800'.
Acidised with 7500 gal. with 40 bbls. oil produced.
Work performed January 30, 1958.
This C-103 has R. Olsen as the operator and requests
that a testing allowable of 40 bbls. per day be made
for February.

-3-
Series No. 5

SUPPLEMENT 50, 1928

Prop fees \$13\15\25
Oil production filing fees: \$5 ppg. to 3 ppg.
Gas production filing fees: \$23.00 MCF to 3 ppg.
Gas - \$8,500.

OCTOBER 8, 1928

FEBRUARY 15, 1929

Packer permits fees varying from \$10 to \$15.
C-103 filing, perforating & acidizing Bimbley zone.
Perf. \$250. to \$800.
Acidizing with 3000 bushels to 10 ppg. Oil produced,
work perforating tanks 30', 10' &
This C-10 as it is often as the operator and leaseholder
will be required to pay to each
for separation.