

NUMBER OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
TRANSPORTER	OIL
	GAS
PRODUCTION OFFICE	
OPERATOR	

## NEW MEXICO OIL CONSERVATION COMMISSION

Santa Fe, New Mexico HOBBS OFFICE O.C.C.

## MISCELLANEOUS NOTICES 2 55 PM '64

strict Office, Oil Conservation Commission, before the work specified is to begin. A copy will be returned to the school on which will be given the approval, with any modifications considered advisable, or the rejection by the Commission or agent, of the plan submitted. The plan as approved should be followed, and work should not begin until approval is obtained. See additional instructions in the Rules and Regulations of the Commission.

Indicate Nature of Notice by Checking Below

NOTICE OF INTENTION TO CHANGE PLANS		NOTICE OF INTENTION TO TEMPORARILY ABANDON WELL		NOTICE OF INTENTION TO DRILL DEEPER	
NOTICE OF INTENTION TO PLUG WELL		NOTICE OF INTENTION TO PLUG BACK		NOTICE OF INTENTION TO SET LINER	
NOTICE OF INTENTION TO SQUEEZE		NOTICE OF INTENTION TO ACIDIZE		NOTICE OF INTENTION TO SHOOT (Nitro)	
NOTICE OF INTENTION TO GUN PERFORATE		NOTICE OF INTENTION (OTHER)		NOTICE OF INTENTION (OTHER)	

OIL CONSERVATION COMMISSION  
SANTA FE, NEW MEXICO

Hobbs, New Mexico

(Place)

August 16, 1964

(Date)

Gentlemen:

Following is a Notice of Intention to do certain work as described below at the.....

**Tidewater Oil Company** **S. J. Sarkay** Well No. **2** in **D**  
(Company or Operator) Lease (Unit)  
**NW**  $\frac{1}{4}$  **NW**  $\frac{1}{4}$  of Sec. **26**, T. **21S**, R. **37E**, NMPM, **Blinebry-Drinkard** Pool  
(40-acre Subdivision)  
**Lea** County.

FULL DETAILS OF PROPOSED PLAN OF WORK  
(FOLLOW INSTRUCTIONS IN THE RULES AND REGULATIONS)

It is proposed to set Baker Model "D" packer at approximately 6390' by wire line. Run long string tail end equipment, disconnect at tubing receptacle and pull out of hole. Run junk basket and perforate Blinebry at approximately 5730-5830', perforations to be picked from GR/N log. Run 3" frac tubing w/retrievable bridge plug, set BP at 5890'. Spot 1000 gal. acid over perforations, set packer at 5700'. Treat Blinebry w/30,000 gal. ref. oil w/1# sand/gal. Swab and test. Drop 3" tubing down, wash out sand, kill well with water, retrieve bridge plug. Run long string with parallel tubing anchor at 5720'. Run short string.

Approved..... 19.....  
Except as follows:Approved  
OIL CONSERVATION COMMISSIONBy.....  
Title.....

Tidewater Oil Company

Original Signed By:

By..... B. M. BRENNING

Position..... Area Engineer

Send Communications regarding well to:

Name..... C. L. Wade

Address..... Box 249, Hobbs, New Mexico