Form 3160-5 (June 1990) UNI...D STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

N.M. OI! ONS. COMMISSION
P.O. BOX 1980 FORM APPROVED MEMICOLURA 1, 1963
Expires: March 31, 1993
5. Lease Designation and Serial No.

	· • · • · • · · · · · · · · · · · · · ·	LC 032096A
	AND REPORTS ON WELLS	6. If Indian, Allottee or Tribe Name
Do not use this form for proposals to drill or to deep		
Use "APPLICATION FOR PERMIT " for s	such proposals	7. If Unit or CA, Agreement Designation
SUBMIT IN TRIPLICATE		and the second s
Type of Well		
X Oil Gas D		
Well Well Other  2. Name of Operator		8. Well Name and No. LOCKHART A-27
CONOCO INC.		WELL # 7 9. API Well No.
3. Address and Telephone No.		<del></del>
10 DESTADR. STE 100W, MIDLAND, TX. 79705 (91	l5) 686 – 5424	30 - 025 - 06806 10. Field and Pool, or Exploratory Area
. Location of Well (Footage, Sec., T., R., M., or Survey Description)  SURFACE: 660' FNL & 1650' FWL, SEC. 27, T 218, R 37E, UNIT LTR 'C' TD:		
		PADDOCK  11. County or Parish, State
y. 10:		LEA, NM
12. CHECK APPROPRIATE BOX(s) TO IND	ICATE NATURE OF NOTICE, REPO	RT, OR OTHER DATA
TYPE OF SUBMISSION	TYPE OF ACT	ION
Notice of Intent	Abandonment	Change of Plans
	Recompletion	New Construction
X Subsequent Report	Plugging Back	Non-Routine Fracturing
	Casing Repair	Water Shut-Off
Final Abandonment Notice	Altering Casing	Conversion to Injection
Final Abandonment Notice		
Final Abandonment Notice	X Other	Dispose Water
Final Abandonment Notice	X Other REPERK & A CIDIZE	Dispose Water (Note: Reportesults of multiple completion on Well
3. Describe Proposed or Completed Operations (Clearly state all pertindirectionally drilled, give subsurface locations and measured and 6-14-95 MIRU. POOH W/ PACKER & TB6 5126-29, 5131-38, 5138-47, 5166-70, 55239-45, 5249-51, 5258-70, TOTAL OF 9	REPERK & ACIDIZE  ent details, and give pertinent dates, including estimated ded true vertical depths for all markers and zones pertinent to:  G. PERF PADDOCK W/1 JSPF @ 5105  172-74, 5178-82, 5186-93, 5196-99  1 HOLES. ACID ZONE C W/ 32 bbl AC	(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) alse of starting any proposed work. If well is this work.)*  5-09, 5116-20, 5122-24, 9, 5204-10, 5213-15, CID W/ 36.9 BALL SEALERS.
3 Describe Proposed or Completed Operations (Clearly state all pertin directionally drilled, give subsurface locations and measured and 6-14-95 MIRU. POOH W/ PACKER & TB6 5126-29, 5131-38, 5138-47, 5166-70, 5	REPERK & ACIDIZE  ent details, and give pertinent dates, including estimated ded true vertical depths for all markers and zones pertinent to 1.05  G. PERF PADDOCK W/ 1 JSPF @ 51.05  1.72 - 74, 51.78 - 82, 51.86 - 93, 51.96 - 99  1.11 HOLES. ACID ZONE C W/ 32 bbl ACO  2.12 BALL SEALERS.GIH W/ PACKER & 2.50	(Note: Report results of multiple completion on Wed Completion or Recompletion Report and Log form.) ate of starting any proposed work. If well is this work.)*  5-09, 5116-20, 5122-24, 0, 5204-10, 5213-15, CID W/ 36 .9 BALL SEALERS.

\*See Instruction on Reverse Side

TECENTERS