

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

P.O. Box Drawer DD, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088

Santa Fe, New Mexico 87504-2088

WELL API NO.	30-025-06830
5. Indicate Type of Lease	STATE ☐ FEE ☒
6. State Oil / Gas Lease No.	
7. Lease Name or Unit Agreement Name	J.N. CARSON (NCT-A)
8. Well No.	1
9. Pool Name or Wildcat	PENROSE SKELLY GRAYBURG
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	3452' GL

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT (FORM C-101) FOR SUCH PROPOSALS.	
1. Type of Well:	OIL WELL ☒ GAS WELL ☐ OTHER ☐
2. Name of Operator	CHEVRON USA INC
3. Address of Operator	15 SMITH ROAD, MIDLAND, TX 79705
4. Well Location	Unit Letter <u>K</u> : <u>1980'</u> Feet From The <u>SOUTH</u> Line and <u>1980'</u> Feet From The <u>WEST</u> Line Section <u>28</u> Township <u>21-S</u> Range <u>37-E</u> NMPM <u>LEA</u> COUNTY
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	3452' GL

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPERATION ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐		CASING TEST AND CEMENT JOB ☐	
OTHER: ☐		OTHER: ☒	DEEPEN TO LOWER GRAYBURG, FRAC STIM

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

2-17-03: MIRU. TIH W/BIT & DC'S.
 2-18-03: TAG @ 3757'. C/O FILL FROM 3757-3780'. DRILL NEW HOLE FR 3780-3785'.
 2-19-03: DRILL NEW 4 3/4" HOLE FR 3785-3815.
 2-20-03: TIH W/INFL PKR ON WS. SET PKR @ 3785. RU SWAB. REL PKR @ 3785. TIH W/BIT & DC'S.
 2-21-03: TAG FILL @ 3814. DRILL NEW 4 3/4" HOLE FR 3815-3842. TIH & SET PKR @ 3815. RU SWAB.
 2-24-03: REL PKR. TIH W/BIT. TAG @ 3842. NO FILL. DRILL NEW O.H. FR 3842-3867'.
 2-25-03: TIH W/PKR & SET @ 3842'. RU SWAB. REL PKR @ 3842. TIH W/PROD PKR & SET @ 3555. PRESS TEST BACKSIDE TO 500 PSI-OK.
 2-26-03: ACIDIZE O.H. W/5328 GALS 15% ANTI-SLUDGE HCL. RU SWAB. CUT OFF BAD SAND LINE.
 2-27-03: RU SWAB. 9 HR TEST. (CHRIS WILLIAMS WITH NMOCD OK'D NOT TO RUN DEVIATION SURVEY @ 2:30 PM)
 2-28-03: SWAB - 1 HR TEST. REL PKR @ 3555. LD PKR. TIH W/BIT & TAG @ 3862. (5' FILL) PUMP 2% KCL FW DN TBG.
 3-03-03: TIH W/BPMA, PERF SUB, SN, TAC, & 114 JTS 2 7/8" TBG. RIG DOWN. TURN WELL OVER TO PRODUCTION TO TEST.

FINAL REPORT

3608-3770' 4 3/4" OPEN HOLE (OLD GRAYBURG)
 3770-3867' 4 3/4" OPEN HOLE (NEW GRAYBURG)

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Denise Leake TITLE Regulatory Specialist DATE 3/4/2003
 TYPE OR PRINT NAME Denise Leake Telephone No. 915-687-7375

(This space for State Use)

APPROVED

CONDITIONS OF APPROVAL, IF ANY:

ORIGINAL SIGNED BY
GARY W. WINK
 TITLE FIELD REPRESENTATIVE II/STAFF MANAGER DATE

DeSola/Nichols 12-93 ver 1.0