

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)	
1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator <b>Gulf Oil Corporation</b>	8. Farm or Lease Name <b>J. N. Carson (NCT-C)</b>
3. Address of Operator <b>Box 670, Hobbs, New Mexico 88240</b>	9. Well No. <b>7</b>
4. Location of Well UNIT LETTER <b>P</b> <b>554</b> FEET FROM THE <b>South</b> LINE AND <b>554</b> FEET FROM THE <b>East</b> LINE, SECTION <b>28</b> TOWNSHIP <b>21-S</b> RANGE <b>37-E</b> NMPM.	10. Field and Pool, or Wildcat <b>Paddock</b>
15. Elevation (Show whether DF, RT, GR, etc.) <b>3439' GL</b>	12. County <b>Lea</b>

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	
OTHER <input type="checkbox"/>		OTHER <input type="checkbox"/>	

Perforated and acidized

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

5300' PB.

Pulled producing equipment. Ran 6-1/8" bit and cleaned out to 5208'. Perforated Paddock zone in 7" casing with 2, 1/2" JHPF at 5245-54'. Ran packer and 2-3/8" tubing. Set Packer at 5220' with 15,000# compression. Treated new perforations with 2500 gallons of 15% NE acid. Flushed with 23 barrels of brine water. Maximum pressure 3650#, minimum 2000#, ISIP vacuum. AIR 4.5 BPM. Swabbed and cleaned up and returned well to production.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED *H. J. Buzgale* TITLE Area Engineer DATE April 17, 1973

APPROVED BY *Leslie A. Clements* TITLE \_\_\_\_\_ DATE \_\_\_\_\_

CONDITIONS OF APPROVAL, IF ANY: