

OIL CONSERVATION DIVISION

P. O. BOX 2038

SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.O.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease
State ☐ Free ☒

5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO OPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

OIL WELL ☒	GAS WELL ☐	OTHER ☐	7. Unit Agreement Name
Name of Operator Chevron U.S.A. Inc.			8. Farm or Lease Name Eunice King
Address of Operator P.O. Box 670, Hobbs, NM 88240			9. Well No. 8
Location of Well UNIT LETTER <u>H</u> 1980 FEET FROM THE <u>North</u> LINE AND <u>660</u> FEET FROM <u>East</u> THE <u>LINE, SECTION 28</u> TOWNSHIP <u>21S</u> RANGE <u>37E</u> NMPM.			10. Fluid and Pool, or Wildcat Paddock
15. Elevation (Show whether DF, RT, GR, etc.) 3435			12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

REPAIR REMEDIAL WORK ☐	PLUG AND ABANDON ☐
IMPROVING ABANDON ☐	CHANGE PLANS ☐
ILL OR ALTER CASING ☐	OTHER ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐	ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐	OTHER <u>Swab tst, run PE to produce top int.</u> ☒

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Work performed 12-4-87 through 12-8-87

POOH w/ prod. equip, set pkr at 5021, swab, rec. 35bbbls wtr, Swab test perf interval 5057-5072, rec 80bbbls, total fl rec 22bbbl oil, 93bbbl wtr. Swab tst perf interval 5094-5205, rec. 95bbbl wtr, cont. swab tst interval 5094-5205, rec 45 bbl wtr, set pkr at 5211, swab tst interval 5234-5258. rec 49bbbl wtr, 8.4bbbl oil. Cont swab tst interval 5234-5258, rec 90bbbls wtr, POOH w/ tbg and pkr, RIH w/ prod equip and 2 3/8" tbg to 5078', SN at 5067', TAC at 4819, ND BOP, NUWH run rods, RIH w/pmp, hang well on, load and tst, ok. RD & rlse rig, turn over to production.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

M. E. Atkins

TITLE Staff Drilling Engineer

DATE Dec. 9, 1987

ORIGINAL SIGNED BY JERRY SEXTON

DISTRICT ENGINEER

COPIES BY DISTRICT ENGINEER

TITLE

DATE

COPIES OF APPROVAL, IF ANY:

RECEIVED

DEC 14 1987

OOD
HOBBS OFFICE