STATE OF NEW MEXICO NERGY AND MINERALS DEPARTMENT

##. #F COPIES ACCEIVES		
DISTRIBUTION	1	Ī
SANTA FE		
FILE		_
U.S.G.S.	1	_
LAND OFFICE		_
OPERATOR		_

OIL CONSERVATION DIVISION P. O. BOX 2088

Form C-103 SANTA FE, NEW MEXICO 87501 Revised 10-1-Sa. Indicate Type of Lease State 5. State Oll & Gas Lease No SUNDRY NOTICES AND REPORTS ON WELLS يندر 🗓 7. Unit Agreement Name WELL ___ :came of Operator 8. Farm or Lease Name Chevron U.S.A. Inc. Eunice King P. O. Box 670, Hobbs, NM 88240 Location of Well 10. Fleid and Pool, or Wildcat UNIT LETTER Paddock 21S 15. Elevation (Show whether DF, RT, GR, etc.) 12. County 3435' Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: SFORM SEMEDIAL WORK CASING TEST AND CEMENT JOS OTHER TA Blinebry, perf Paddock Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed

TD 6627'

POOH w/rods, pump and tubing. Log 6200-4500'. Set CIBP at 5500', test to 1000 psi-ok. Perf 5057-59',5064-66',5070-72',5094-96',5104-06',5119-21',5142-44',5162-64',5172-74', 5186-88',5203-05',5234-36',5246-48',5256-58' $\text{w/(2)} \stackrel{1}{\scriptstyle 2}\text{"}$ JHPF. Spot 300 gal 15% NEFE HCL across perfs. Acidize w/5000 gals 15% NEFE HCL w/add, dropping (84) 1.1 RCNB's evenly through first 4500 gals acid; flush w/500 gal acid and disp w/8.6 GKF. Swab. GIH w/ pump and rods; space well and hang on. Work performed 10-13-87 through 10-15-87.

I hereby certify that the information above is true and complete to the best of my knowledge and belief. Eddie W. Seay Oil & Gas Inspector