
TENERGY AND MINERALS DEPARTMENT

HO: OF COPIES RECEIVED	1	
DISTRIBUTION		
SANTA PE		
TILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

JIL CONSERVATION DIVISION

Form	C-1	03	
David	t a d	10.	1 . 7

P. O. BOX 2088	Form C-103		
SANTA FE, NEW MEXICO 87501	Revised 10-1-7		
FILE	5a. Indicate Type of Leuse		
U.S.O.S.			
LAND OFFICE	State Fee X		
OPERATOR	5. State Oil & Gas Lease No.		
	mmmm		
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL ON TO DEEPEN ON PLUG BACK TO A DIFFERENT RESERVOIR.			
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)	7. Unit Agreement Name		
oil GAS WELL OTHER- Oil/Gas Dual			
ARCO 011 & Gas Company	8. Farm or Lease Name		
Division of Atlantic Richfield Co.	J.R. Cone "R"		
P.O. Box 1710, Hobbs, NM 88240	9. Well No.		
Location of Well	10. Field and Pool, or Wildcat		
UNIT LETTER 0 660 FEET FROM THE SOUTH LINE AND 1980 FEET FROM	Blinebry Gas Drinkard		
Foot 26 210 277			
THE East LINE, SECTION 26 TOWNSHIP 21S RANGE 37E HMPM.			
15. Elevation (Show whether DF, RT, GR, etc.)	12. County		
3376' GR	Lea		
Check Appropriate Box To Indicate Nature of Notice, Report or Other	er Data		
NOTICE OF INTENTION TO: SUBSEQUENT			
Blk & Blank off			
PERFORM REMEDIAL WORK X LOWER Bly PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING		
TEMPORARILY ABANDON X Drkd COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT		
PULL OR ALTER CASING CASING TEST AND CEMENT JOB	· ·		
OTHER			
OTHER	era		
.7. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including e-wark) SEE RULE 1103.	stimated date of starting any proposed		
1. Rig up, kill Bly & Drk zones, install BOP, POH w/dual comp assy.			
2. Set & test plug in Model D pkr @ 6290'. Set retr BP @ +5680'.			
3. Set pkr @ approx. 5450', treat Bly perfs 5476-5637' w/5000 gals 7\%	MSR acid & 1000		
SCF/bbl. Nitrogen, disp1 w/33 bbls slick 2% KCL wtr. Swab & test.			
4. If necessary, frac perfs 5476-5637' w/30,000 gals of WF 30 pad & 20	.000 gals 15% gelled		
acid in 2 stages, disp1 w/10,000 gals WF 30 F/flush & overflush w/40	00 SCF/bbl. Nitrogen		
thru out all fluids. Swab & test	· · · · · · · · · · · · · · · · · · ·		
5. POH w/pkr. RIH w/single strg of 2-3/8" OD tbg & retrievable product approx. 5380'.	ion pkr. Set pkr @		
6. Connect up well head & produce as single completion in the Blinebry	Cas interval		
5476-5637'.	Gas Interval		
	•		
	•		
16. I hereby certify that the information above is true and complete to the best of my knowledge and belief.			
AIGHED DIST. DIST. DIST. DIST.	4-22-81		
C Signed ha			
Orig. Signed by Les Clements	The State of		
Oil & Gas Insp	DATE		
CONDITIONS OF APPROVAL, IF ANY:			



ARCO Oil & Gas Company
Division of Atlantic Richfield Company
Blow Out Preventer Program

lease 'Nar	ie	J.	R.	Cone	"B"			
Well No.		2					····	***************
Location	660.	FSL	& :	1980'	FEL,		-	Selferantia Regularian
	Sec	26-21	S-	37E, 1	ea Co	., N	M	The state of the s

BOP to be tested before installed on well and will be maintained in good working condition during drilling. All wellhead fittings to be of sufficient pressure to operate in a safe manner.