

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department
OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

Form C-103
Revised 1-1-89

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

P.O. Drawer Dd, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, Nm 87410

API NO. (assigned by OCD on New Wells)	
30-025-06865	
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>	
6. State Oil & Gas Lease No. N/A	
7. Lease Name or Unit Agreement Name EUNICE KING	
8. Well No. 25	
9. Pool name or Wildcat BLINEBRY	
10. Elevation (Show whether OF, RKB, RT, GR, etc.) 3460' GE	

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL <input type="checkbox"/> GAS <input type="checkbox"/> WELL <input type="checkbox"/> WELL <input checked="" type="checkbox"/> OTHER <input type="checkbox"/>	
2. Name of Operator CHEVRON U.S.A. INC.	
3. Address of Operator P.O. BOX 1150 MIDLAND, TX 79702 ATTN: P.R. MATTHEWS	
4. Well Location Unit Letter <u>D</u> : <u>990</u> Feet From Th <u>NORTH</u> Line and <u>990</u> Feet From The <u>WEST</u> Line Section <u>28</u> Township <u>21S</u> Range <u>37E</u> NMPM <u>LEA</u> County 10. Elevation (Show whether OF, RKB, RT, GR, etc.) 3460' GE	

11 Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	
OTHER: <u>S</u>	
SUBSEQUENT REPORT OF:	
REMEDIAL WORK <input type="checkbox"/>	ALTER CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABAN. <input type="checkbox"/>
CASING TEST AND CMT JOB <input type="checkbox"/>	
OTHER: <u>RECOMPLETE IN BLINEBRY</u>	<input checked="" type="checkbox"/>
<u>abandon Paddock</u>	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including
estimated date of starting any proposed work) SEE RULE 1103.

MIRU, TIH TO 5390'. SET PACKER AT 5048', EST. INJECTION INTO PADDOCK PERFS.
TIH SET CIGR AT 5015', PUMP 100 SXS CMT INTO CIGR AND SQZ. OFF PADDOCK PERFS.
DRILL OUT CMT. AND CIGR TO 5410. TEST CIBP AT 5410', TEST FAILED.
DRILL OUT CIBP AT 5410 AND SET NEW CIBP AT 5780', CAP WITH 35' OF CEMENT. NEW PBTD AT 5745'
PERF 7" CSG AT 5525'-5704', 23 HOLES, ACDZ WITH 2688 GALS. OF 15% NEFE. SWAB/BACK ACID.
FRAC BLINEBRY PERFS AT 5525-5704 WITH 38,000 GALS OF 50/50 X-L GEL & 100,000 # OF SAND.
FLOW WELL BACK.
SET PACKER AT 5479' AND BEGIN PRODUCING ON 5-27-92.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.			
SIGNATURE	<u>P.R. Matthews</u>	TITLE	TECH. ASSISTANT
DATE:		5-28-92	
TYPE OR PRINT NAME		P.R. MATTHEWS	
TELEPHONE NO		(915)687-7812	
Original filed by <u>Paul Smith</u>			
APPROVED BY	<u>Paul Smith</u>	TITLE	
CONDITIONS OF APPROVAL, IF ANY:			
DATE			

3