STATE OF NEW MEXICO ENERGY AND MINERALS DEPARTMENT	
OIL CONSERVATION DIVISIO	) NI
DISTRIBUTION P. O. BOX 2088	Form C-103
SANTA FE, NEW MEXICO'87501	Revised 10-1-7:
U.S.J.S.	Sa. Indicate Type of Lease
LAKD OFFICE	State Fee X
OPENATOR	5. State Oil 6 Gas Lease No.
SUNDRY NOTICES (NED DEPODED ON WELL	
SUNDRY NOTICES AND REPORTS ON WELLS 100 NOT USE THIS FORM FOR PROPOSALS TO ORILL ON TO DEEPEN OR PLUG BACK TO A DIFFERENT RESE USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)	7. Unit Agreement Name
OIL GAB OTHER-	i ener here home
2. Name of Operator	8. Farm or Lease Ivame
Mobil Producing TX. & N.M. Inc.	E. O. Carson
Nine Greenway Plaza, Suite 2700, Houston, Texas 77046	9. Well No.
4. Location of well	10. Field and Pool, or Wildcat
UNIT LETTER N 518.6 FLET FROM THE South LINE AND 2121.4	THE OFT & O
	A A A A A A A A A A A A A A A A A A A
THE West LINE, SECTION 28 TOWNSHIP 215 RANGE 37E	
15. Flevation (Show whether DF, RT, GR, etc.)	
3451 GR	Lea
16. Check Appropriate Box To Indicate Nature of Notice, R	
	JBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK	<b>[</b>
TEMPORARILY ABANDON	
PULL OR ALTER CABING CHANGE PLANE CASING TEST AND CEMEN	
OTHER	Plug Back
17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent do wprk) SEE RULE 1703.	tes, including estimated date of starting any proposed
TD 8134	
05/03/84 MIRU Cardinal WS DD Ut, unseated pump, POH w/rods &	NU ROP NOT TAC
HOC WCI YOWN LDY W//S DDIS TY WTY, POH W/ 2-3/8 +6a	-
- 03/04/04 UIN W/ 4-3/4 DIT, US & 258 its 2-3/8 that to 2002 Do	H, GIH w/ HOWCO 5-1/2 cmt
1000010000000000000000000000000000000	
8112-8135, HOWCO sqz cmt Ellen perfs w/50 sxs Class H neat, pull stinger to 7965 & dump 63' of cmt on top of cmt ret, rev out 1 sx cmt, HOWCO spot 50 bbls	
$\gamma \gamma $	$i \circ \circ \sigma$
	2 - 2/9 + ba = 0 + a = 0 - coop
06/84 POH w/CIBP, GIH w/ 4-3/4 bit, 5-1/2 CS on 2-3/8 tbg & to 6100.	stop @ 6020 & work bit
05/07/84 RIH w/ 4-3/4 bit + CS + DCs on 2-3/8 tbg, tagged @ 6105, drld cmt stringers 6105 to 6152, ran bit to 6457, POH w/ tbg & bit, RIH w/ HOWCO 5-1/2 CIBP,	
Set CIDF @ 0390, HOWLU SPOT 15 SXS (lass H heat cmt on top (IRD pulled the	
05/08/84 Dresser ran Lifetime-Neutron Log, GR-Collar Log from 05/09/84 RIH w/ tbg tagged TOC @ 6390, HOWCO spot 15x Class H @ 6334. displ hole w/160 bblc 2% KCl 6	6391-4390.
(1000)	
	ik.
SEE REVERSE 18.1 hereby certify that the information above is true and complete to the best of my knowledge and belief	
( ) A A A A	· · · · · · · · · · · · · · · · · · ·
Authorized Agent	DATE 06/27/84
	DATE00/2//84
ORIGINAL SIGNED BY JERRY SEXTON	HATE JUI 1 8 1984
CONDITIONS OF APPROVAL, IF ANY:	DATE JUL 10 1304
· · · · · · · · · · · · · · · · · · ·	

7N

#17. Continued from front.

05/10/84 SD WO perfs.

RIH w/ 5-1/2" pkr & DH shut off valve + 2-3/8 SN + rec (on/off tool w/1.875 05/11/84 "F" profit nipple on 189 jts 2-3/8 tbg to 5940, Dresser Atlas attempted to Core Log Dept prior to setting pkr, tool set down @ 5927, work down hole shut off valve, attempt to run collar loc same results, attempt to rev circ annl press to 1000 psi, rel from recptical, rev circ w/30 bbls 2% KCl wtr, latched onto receptical, attempt run collar loc, same results, rel & POH w/pkr.

1 1

- RIH w/ pkr + DH shut off valve + Recpt w/nipple on 189 jts 2-3/8 tbg, Dresser 05/12ran collar loc, set pkr @ 5939, Corr to logs, press annl to 500 psi/15 min/held 13/84 ok, swab, Dresser perf 5-1/2 csg w/2JSPF in Tubb form @ 5952-5962, 5980-5996 =54 holes, job compl @ 4 PM 5/12/84, swab, left overnight.
- HOWCO spotted 300 gals MOD-101 acid 4398-5996, POH w/coil tbg, acidized Tubb 05/14/84 perfs 5952-5996 down 2-3/8 tbg w/spot acid flushed w/34,000 SCF/N2, job compl 0 6:30 PM.
- Repair flowline, left well open to prod facilities. 05/15/84
- HOWCO acidized Tubb perfs 5952-5996 w/5000 gals MOD-101 70 quality acid + 55 05/16/84 RCNBS, + 10,000 SCF/N2 Pre-Pad, flushed w/33,000 SCF/N2, job compl @ 8:30 AM, open well to test tank.
- Swabbing & testing well. 05/17-
- 21/84

## Perf w/1JSPF @ 5999-6004, 6012-6014, 6017-6028, 6067-6086, 6104-6111, 6145-6148, 05/22/84 6152-6156, 6160-6169, 6192-6201, 6274-6286 (92 holes), job compl @ 1:30 PM

- Left open to test tank. 05/23/84
- HOWCO acidized Tubb perfs 5952-6286 w/10,000 MOD-101 70 quality acid + 70 RCNBS, 05/24/84 fl w/34,000 SCF/N2 quality +230 RCNBS + 10,000 SCF/N2 Pre-Pad + 70 RCNBS, fl w/34,000 SCF/N2, job compl @ 9:30 AM.
- Left well open to test tank. 05/25-

28/84

- POH w/ tbg, ND BOP, spaced out w/28' 2-3/8 tbg subs (3 2-3/8x6' + 2 2-3/8 05/29/84 x4'), latched onto EL recpt, attm to open DH valve, rel pkr, reset pkr @ 5940, Open DH valve, NU wellhead, tied well into flowline, prod tech ran Sonic fl level, FL @ 3797, RD & rel Cardinal WS & well to prod @ 3:30 PM.
- 05/30/84 Testing well. Tubb perforations 5952-6286.

## RECEIVED

101 5 - 1984