DISTRIBUTION SANTA FE		
<del></del>		Form C-103
SANTA FE		Supersedes Old
	NEW MEXICO OIL CONSERVATION COMMISSION	C-102 and C-103 Effective 1-1-65
FILE		
U.S.G.S.		5a. Indicate Type of Lease
LAND OFFICE		State Fee X
OPERATOR		5. State Oil & Gas Lease No.
SUNDRY NO (DO NOT USE THIS FIRM FOR PROPOSAL USE "APPLICATION FO	TICES AND REPORTS ON WELLS  TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  R PERMIT - " (FORM C-101) FOR SUCH PROPOSALS.)	
	HER-	7. Unit Agreement Name
2. Name of Operator Atlantic Richfield Company		8. Farm or Lease Name
3. Address of Operator		W.H. Turner
P.O. Box 1710 - Hobbs, New	Mexico 88240	9. Well 100.
4. Location of Well		10. Field and Pool, or Wildcat
UNIT LETTER K 990	FEET FROM THE NORTH LINE AND 1650 FEET FR	Democra Classic C.
THE West INE, SECTION	29 TOWNSHIP 21S RANGE 37E NMP	
	15. Elevation (Show whether DF, RT, GR, etc.)	12. County
	3472' DF	Lea
Check Appro	opriate Box To Indicate Nature of Notice, Report or C	Other Data
NOTICE OF INTEN		NT REPORT OF:
<b>—</b> 3		
PERFORM REMEDIAL WORK	PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON	COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT
PULL OR ALTER CASING	CHANGE PLANS CASING TEST AND CEMENT JOB	
	OTHER Shut-in	X
OTHER		
	ns (Clearly state all pertinent details, and give pertinent dates, includi	ng estimated date of starting any proposed
17. Describe Proposed or Completed Operation work) SEE RULE 1103.  The above well was shut-	in on June 10, 1970. The well was shut-in Plans are to recomplete to the Eumont Gas	because it was
17. Describe Proposed or Completed Operation work) SEE RULE 1103.  The above well was shut-uneconomical to produce,	in on June 10, 1970. The well was shut-in	because it was
17. Describe Proposed or Completed Operation work) SEE RULE 1103.  The above well was shut-uneconomical to produce, of 1976.	in on June 10, 1970. The well was shut-in Plans are to recomplete to the Eumont Ga:	because it was s during the 1st qtr
17. Describe Proposed or Completed Operation work) SEE RULE 1103.  The above well was shut-uneconomical to produce, of 1976.	in on June 10, 1970. The well was shut-in Plans are to recomplete to the Eumont Gas  £ \( \psi_i \)	because it was s during the 1st qtr
17. Describe Proposed or Completed Operation work) SEE RULE 1103.  The above well was shut-uneconomical to produce, of 1976.	in on June 10, 1970. The well was shut-in Plans are to recomplete to the Eumont Gas $\mathcal{E}_{\mathcal{H}}$	because it was

CONDITIONS OF APPROVA ., IF ANY: