NO. OF COPIES RECEIVED						~	rm C+101	
DISTRIBUTION		NEWN	EXICO OIL CONSE	RVATION CO	MWISSION		rm C+102 evised 1-1-65	
SANTA FE						5	A. Indicate	Type of Lease
FILE						1	STATE	
U.S.G.S.	44					.5	. State Oil 6	Gas Lease No.
LAND OFFICE								
OPERATOR							mm	mmmm
			DECEDEN		ACK	{		
	I FOR PERM	IT TO I	DRILL, DEEPEN,	UR PLUG E	ACK		Unit Agree	ment Name
1s. Type of Work							-	
			DEEPEN 🕅	•	PLUG B		Form or Le	ase Name
b. Type of Well					MULT	IPLE []]		IA HARDY
OIL XX GAS WELL	OTHER			BINGLE ZONE	1		Well No.	
2. Name of Operator							1	
MOBIL PRODUCING T	X. & N.M.	INC.			- <u></u>			Pool, or Wildcat
3, Address of Operator						1		
NINE GREENWAY PLA	ZA, SUITE	2700,	HOUSTON, TEXA	<u>IS 77046</u>			PADDUCK	(PADDOCK)
4. Location of Well	E		2310	FEET FROM THE	<u>NORTH</u>	LINE		
UNIT LETTER						3	//////	
AND 330 FEET FROM	THE WEST	LIN	C OF SEC. 29	TWP. 215	RGE. 37		2. County	
	MIIIII	\overline{UU}			///////			
					TITTT	MMM	LEA	
*****************	iiiiiiii	ttttt		mm	111111			
<u> </u>		11111			//////	111111	TITI	20. Rotary or C.T.
81111111111111111	////////	$\pi\pi$	MIIIIIII	19. Proposed I	Depth 19	A. Formation		• •
		MM		5400		PADDO	CK	ROTARY
21. Elevations (Show whether DF,	RT, etc.) 21	A. Kind	& Status Plug. Bond	21B. Drilling (Contractor			. Date Work will start
3483-GROUND		ON F	ILE	UNKNOW	IN		ASA	<u>P</u>
23.			ROPOSED CASING AN	D CEMENT PR	OGRAM			
		F				T		
SIZE OF HOLE	SIZE OF C	ASING	WEIGHT PER FOO	T SETTING	DEPTH	SACKS OF	CEMENT	EST. TOP
EXISTING 11"	9-5/8"		40#	1344		310		SURFACE
	the second s			1 000		175		

EXISTING_11" 8-½"	<u>9-5/8"</u> 7"	<u> </u>	2625'	175	2070'
PROPOSED	5-½" LINER	15.5#-K-55	5400'	CIRCULATE	SURFACE

This well is presently completed as a non-commercial producer in the Penrose Skelly Grayburg Pool. Permission is requested to abandon this zone, deepen to 5400', set liner from top to bottom and complete in the Paddock. Procedures for completing this work are attached.

Signed Alton A. D. BOND Tille REGULATORY TECHNICIAN SUPERVI		
(This space for State Use) ORIGINAL SIGNED BY JERRY SEXTON	MAY 281	984

STATE OF NEW MEXICO

C L CONSERVATION DIVISION

P. O. BOX 2088

Form C-102 Revised 10-1-78

ENERGY AND MINERALS	DEPARTMENT	SANTA F	E. NEW	MEXICO 8	7501		Revised 10-1-78
		All distances must be	from the oute	r boundaries of	the Section		L W. IL MA
Operator		110		IA HARDY			Well No.
MOBIL PRODUCING		INC.	Hange		County		
F Section		215		37E		LEA	
Actual Postage Location of							······································
	from the WES'	line and	2310	lec	ot from the	NORTH	line
Ground Level Elev.	Producing Format		Poul	DADDOCK			Dedicated Acreage: 40
3483	PADDO	<u> </u>	<u> </u>	PADDOCK			HU Acres
interest and roy 3. If more than one dated by commu Yes If answer is "n	ne lease is de alty). 2 lease of diffe nitization, unit No If answ o;" list the own	dicated to the wel rent ownership is ization, force-pool er is "yes;" type o	l, outline dedicated ing. etc? of consolid	each and ide to the well, lation	have the	ownership the	ercof (both as to working all owners been consoli- ted. (Use reverse side of
this form if nece No allowable wi forced-pooling, c	ll be assigned (o the well until al until a non-standar	l interests d unit, eli	have been o minating suc	consolidat ch interest	ed (by comm s, has been a	nunitization, unitization, approved by the Division
	1		1				CERTIFICATION
, 0						toined here	ertify that the information con- sin is true and complete to the knowledge and belief. TB-O-N
2 			 			Company M Date	D. BOND y Technician Supervi obil Producing X. & N.M. Inc.
And and a substant of the substant of the	L	<u></u>	!				
	<i>T 215</i>	R37	E 			shown on t notes of o under my s	certify that the well location his plat was plotted from field actual surveys made by nie or upervision, and that the same d correct to the best of my and belief.
						Date Surveye Registered P and/or Land	rotessional Engineer
2 330 660 PO 1	20 10 NO 10 R() 2	510 2640 2000	1300	1	а 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3	Certificate N	0.

WORKOVER PROCEDURES FUR MOBIL PRODUCING TX. & N.M. INC.

CORDELIA HARDY WELL #1 UNIT E, SEC. 29, T21S, R37 E LEA COUNTY, NEW MEXICO

- 1) MIRU PU. POH w/ rods & pump.
- 2) NU BOP & Test. (8"-3000# Mechanical type BOP w/ Master Gate & Pipe Rams). POH w/ Tbg.
- 3) MIRU Reverse Unit. GIH w/ 6-/8" Bit & 4½". Drill Collars. Displace hole w/ 2% KCl. Wtr.
- 4) Drill 6-1/8" hole to 5400' w/ 2% KCl Wtr. (Note, if lost circ occurs in Penrose Skelly Grayburg zone, sqz. as necessary prior to continuing drilling.)
- 5) Circ. & condition hole 2-4 hrs. prior to logging. POH.
- 6) Run OH logs as follows:

MWDeer 5/14/84

•

- Run 1: GR + Compensated Neutron 5400' to Surface + Formation Density + Caliper (minimum 3 arm caliper required). - 5400 to 3625'.
- Run 2: GR + BHC Sonic + Caliper 5400' to 3625'.

Run 3: GR + DLL + Microlog - 5400' 3625'.

- 7) GIH & condition 2 hrs. w/ 2% KCl Wtr. POH.
- 8) GIH w/ Float Shoe + 1 jt + 4½" csg + Float Collar + 4½" csg. (Run centralizers every other jt on bottom 4 jts. + every jt 100' above & below potential pays). Run csg from TD (=5400') to surface.
- 9) Cmt csg to surf. w/ Howco Lite CL H w/ 1/4# Flocele/sx (+ 12.7#/gal., 1.84 cu.ft./sx yield) + ClC w/ .3% Halad 9 from 5400' to 4900'. (20 to 30% excess above hole vol. up to 7" csg shoe @ 3625'). Reciprocate csg while cmt'ing, if possible.
- 10) WOC, min. 12 hrs. Drill out to TD & Test csg prior to perfing.
- 11) Perf. as directed Prod Geol. to choose perf's.