## NEW MEXICO OIL CONSERVATION COMMISSION Santa Fe, New Mexico

## MISCELLANEOUS NOTICES

Submit this notice in TRIPLICATE to the District Office. Oil Conservation Commission, before the work specified is to begin. A copy will be returned to the sender on which will be given the approval, with any modifications considered advisable, or the rejection by the Commission or agent, of the plan submitted. The plan as approved should be followed, and work should not begin until approval is obtained. See additional instructions in the Rules and Regulations of the Commission.

	Indicate Nature of Notice by	Checking Belo	<b>W</b>		
otice of Intention Change Plans	Notice of Intention to Temporarily Abandon Well		Notice of Intention to Drill Deeper	ИС	
OTICE OF INTENTION PLUG WELL	Notice of Intention to Plug Back		Notice of Intention to Set Liner	И	
otice of Intention Squeeze	Notice of Intention to Acidize	11		Notice of Intention to Shoot (Nitro)	
otice of Intention Gun Perforate	Notice of Intention (Other)	I	Notice of Intention (Other)		
IL CONSERVATION COMMISSION OF THE NEW MEXICO	ON Hobbs, New Mexic	10	Ме	rch 16, 1962	
	to do certain work as described below				
	y, Inc. C. Hardy 2		Well No	in	
(Company or O	29 , T 21 S , R 37	E ZWOW	Penrese Si	telly (U	nit)
(40-acre Subdivision)	, 1,, 1,		•		
Perfs: Open Hele 362	reverse circulating equip	pment and			
and pressure test. Fi	no w/20.000 gals lease c	rade + 40.	.000# 20 <b>-40 me</b> :	sh sand in tw	
and pressure test. Fr					
stages using 1800# met	th balls as plugging agent	t and 1000	# Adomite. U		<b>*•</b>
stages using 1800# met		t and 1000	# Adomite. U		<b>1</b> •
stages using 1800# met and pull tbg. Rerum 2	th balls as plugging agent on the third, reds & pump. Ten	t and 1000 st and con	# Adomite. U	aseat packer	
stages using 1800# met and pull tbg. Rerun 2	th balls as plugging agent on the third, reds & pump. Ten	t and 1000 st and con	# Adomite. Un	Inc.	
stages using 1800# met and pull tbg. Rerun 2	th balls as plugging agent  PH tbg., reds & pump. Ter  Soc	and 1000 st and cor cony Mobil	# Adomite. Unaplete.	Inc.	
stages using 1800# met and pull tbg. Rerun 2  pproved	th balls as plugging agent  th balls as plugging agent  the balls as plugging agent  Test  Soc	and 1000 st and con cony Mobil	# Adomite. Unaplete. Oil Company.	Inc.	
stages using 1800# met	th balls as plugging agent  th balls as plugging agent  the balls as plugging agent  Test  Soc	cony Mobil	# Adomite. Unaplete. Oil Company. Company.operation Clerk	Inc.	

Address