

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANITARY	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO RE-OPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE APPLICATION FOR PERMIT - "M" (FORM C-101) FOR SUCH PROPOSALS.)

1. ☐ OIL WELL ☒ GAS WELL ☐ OTHER

2. Name of Operator
Sun Oil Company

3. Address of Operator
P.O. Box 1861 - Midland, Tx. 79702

4. Location of Well
UNIT LETTER **H** **2310** FEET FROM THE **North** LINE AND **330** FEET FROM
THE **East** LINE, SECTION **29** TOWNSHIP **21S** RANGE **37E** NMPM.

15. Elevation (Show whether DF, RT, GR, etc.)
3472 GR.

5a. Indicate Type of Lease
State ☐ Fee ☒

5. State Oil & Gas Lease No.

7. Unit Agreement Name

8. Form of Lease Name
Linam-Hardy Com.

9. Well No.
2

10. Field and Pool, or Wildcat
Elinebry (Gas)

12. County
Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐	OTHER ☒ Add Perf to Present Reservoir & Complete in Tubbs as Dual	CASING TEST AND CEMENT JOBS ☐	
		OTHER ☐	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- MIRU Kill tbq. Bled pres off csg. Remove WH Install BOP.
- POH w/tbg. & pkr.
- GIH w/Baker RBP, Mod "R" DG pkr & SN on 2-3/8" tbq.
- Set BP @ 3620. Set pkr @ 3600. Test BP to 2500#. Reset pkr @ 2800. Dump 2 sks sand on BP. Test csg to 1000#.
- EIR Halliburton sqz Eumont perms 2920-3564 (96 Holes) w/300 sks Class H cmt to 2500# walking sqz pres; reverse hole clean from 2800. Reset pkr @ 2750, pres to 1000# & leave SI for 1 hr.
- POH.
- GIH w/4-3/4" bit on 2-3/8" tbq. Drill & CO to BP. Pres test sqz to 1000#. Circ hole clean w/2.0% KCl water w/2 gal Pen-5/1000 gal.
- POH w/bit. (Cont on Next Page)

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED *Cassand Muntel* TITLE Office Assistant DATE 6/8/77

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: