

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

HOBBS OFFICE O. O. O.

MAY 10 3 02 PM '66

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER - Dual - Sunray DX, V. Linam #2 PS.		7. Unit Agreement Name Central Drinkard Unit
2. Name of Operator Gulf Oil Corporation		8. Farm or Lease Name
3. Address of Operator Box 670, Hobbs, New Mexico		9. Well No. 106
4. Location of Well UNIT LETTER B , 660 FEET FROM THE North LINE AND 1980 FEET FROM THE East LINE, SECTION 29 TOWNSHIP 21-S RANGE 37-E NMPM.		10. Field and Pool, or Wildcat Drinkard
15. Elevation. (Show whether DF, RT, GR, etc.) 3475' GL		12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

Abandoned Drinkard

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

6670' TD, 3888' PB.

Form C-103, dated April 25, 1966 stated our proposed plan: to repair communications, which was unsuccessful. Permission obtained from Mr. Joe D. Ramey May 6, 1966 to abandon the Drinkard zone as follows: Pulled rods and tubing from Penrose Skelly. Could not release long string of tubing from Model D packer at 6490'. Ran free point and found tubing free at 4700'. Cut tubing with chemical cutter at 4695' and POH. Ran fishing tools and jarred 1 hour with 38000#. Tools slipped off fish. Reran over shot with 36" skirt added. Jarred on fish 30 minutes and tools slipped off. Pulled all tools and tubing. Ran 7" Baker retrievable BP and set at 3900'. Dumped 24 gallons of 3/8" pea gravel with dump bailer on top of BP. Estimated FBTD 3888'. Ran tubing, rods and pump in Penrose Skelly. Turned well back to Sunray DX (Penrose Skelly). Drinkard zone, operated by Gulf, to be carried as temporarily abandoned.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED _____ TITLE **Area Petroleum Engineer** DATE **May 9, 1966**

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: