

H&F. Mattara (NCT-B) No. 6 - Detail acct. of work done (Cont'd.)

LM & ppd into form 2-1/2 bpm. TP 1200# TP 9# 12 min after shut down. Fld. tbg, pkr & retr hd. Circ. sd & ball sealers off top of BP. Displ 229 BNB w/287 bo. Retr BP. POH. Ran tbg. seal nip and latch. into pkr 5932'. Tstd tail pipe, tbg & seal nip w/1000#. NDIP. Unable to get below shifting tool & 6474' w/sinker bars. Rel receipt from pkr. PT & tail pipe. Changed well hd.. CO debris. Ran 2-3/8" tbg & tail pipe same as before w/GOE valve in open pos. (jar up to close) latched into pkr at 5932'. Load. tbg w/10 bo Ppd 9 bo into Drk oil some lbpm. TP 2000#. 5 min SIP 1000#. No ind. of comm. into Bl oil zone. Landed tbg w/12,000# tension.

Drk. conn well, swbd 42 BLO no bw 2-3/8" tbg 7 hrs. Swbd dry. TP 600# Drk. CP 50# Bl. Oil. Drk. fld. 1 BLO, no bw 2-3/8" tbg 1 hr. died. Swbd 5 BLO. TP 740# Drk. CP 50# Bl. Oil.

Temp. abandon drinkard and Blinberry oil zones & recomplete in Paddock. Kld. well with 100 bsw. Inst BOP. Released receipt. from pkr. Fld 2-3/8" tbg & tail pipe. Dropped trip bob on pkr at 5932'. Ran ga ring & JB to 5931'. Dapd 2 sx cem. on top of trip bob. Ran 7" CI BP on WL & set at 5270'. Dpd. 2 sx cem. on top of BP. Load. hole w/52 bsw. Tstd 7" csg. & plug w/1000#, OK. Calc. top cnt. at 5261'. Perf. 7" csg. 5241 to 5248' w/2, 1/2" JHPF. Ran 7" pkr & SN on 2-3/8" tbg. Displ. 100 BSW w/200 bo. Displ. 2l bo spotting acid. Set pkr 5178', tbg 5248'. Acidised thru 7" csg. perfs 5241 to 5248' down 2-3/8" tbg. w/500 gals 15% NEA. TP 2400-2800#. CP 500# applied. Flashed w/24 bo. Air 2 bpm. Swbd 84 bo 12 BAR 48 bw 2-3/8" tbg. 5 hrs 6P 11th. 3 RPH from 5120' TP 25# CP 0# pkr. All acid residue recov. plus 48 bbls. new water.

5264' corrected PB. Swbd no BLO 28 bw 2-3/8" tbg. 2 hours. 3 RPH from 5120', FL 4120'. Unsent. pkr. POH. Ran GR & JB to 5264'. Ran 7" CI BP on WL & set at 5225'. Perf. 7" csg. 5162-5175' w/2, 1/2" JHPF. Ran pkr. & SN on 2-3/8" tbg. 451 BLO will not be recovered.

Released pkr, displ. 187 BLO w/18# BSW. POH. Installed well head. Temporarily abandoned after attempt to obtain production from Paddock (previous attempt at Bl. Oil - Drk Oil Dual Unsuccessful)

THE COMMISSION MUST BE NOTIFIED
BY RETURNING THIS FORM C-103
AS TO THE WELL STATUS AND YOUR
FUTURE PLANS FOR THIS WELL.

[illegible][illegible][illegible][illegible]

attempt to obtain production from Redhook (previous attempt at El. Hill - Drk Oil and Reserves - Temporarily abandoned after a

CHIEF OF POLICE
CITY OF NEW YORK
JULY 1964