

Submit 3 Copies To Appropriate District Office

**District I**

1625 N. French Dr., Hobbs, NM 88240

**District II**

1301 W. Grand Avenue, Artesia, NM 88210

**District III**

1000 Rio Brazos Rd., Aztec, NM 87410

**District IV**

1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-103  
Revised March 25, 1999

WELL API NO.  
30-025-06909

5. Indicate Type of Lease

STATE ☒ FEE ☐

6. State Oil & Gas Lease No.

7. Lease Name or Unit Agreement Name:

V.M. Henderson

8. Well No.  
3

9. Pool name or Wildcat  
Blinebry

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

Oil Well ☒ Gas Well ☐ Other ☐

2. Name of Operator  
Chevron USA, Inc.

3. Address of Operator  
15 Smith Rd. Midland, Tx 79705

4. Well Location

Unit Letter H : 1980 feet from the north line and 660 feet from the east line

Section 30 Township 21-S Range 37-E NMPM County Lea

10. Elevation (Show whether DR, RKB, RT, GR, etc.)

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐ CHANGE PLANS ☐

PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☒

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

1. Tag 5 1/2 CIBP @ 5475 spot 50sx plug 5475-5050(Blinebry,Paddock) Tag @ 5029
2. Displace hole w/MLF 9.5# Brine w/25# Gel P/BBL.
3. Spot 30sx plug 4010-3750(Penrose-Skelly)
4. Spot 35sx plug 2925-2600(8 5/8 shoe, B-salt) Tag @ 2582
5. Perf 4 holes @ 310 sqz w/150sx fr/310-surf 5 1/2 X 8 5/8 csg(13 3/8 shoe) Tag @ surf
6. install dry hole marker 11-20-02

Approved as to Plugging of the Well Bore.  
Liability under bond is retained until  
Surface restoration is completed.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE [Signature] TITLE MANAGER/SUNSET DATE 11-20-02

Type or print name Jimmy BAGLEY Telephone No. 915 520-8756

(This space for State use)  
ORIGINAL SIGNED BY  
CHRIS WILLIAMS

APPROVED BY OC DISTRICT SUPERVISOR/GENERAL MANAGER DATE DEC 13 2002

Conditions of approval, if any: