

Submit 3 Copies To Appropriate District
Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 South First, Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
2040 South Pacheco, Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION
2040 South Pacheco
Santa Fe, NM 87505

Form C-103
Revised March 25, 1999

WELL API NO. 30-025-06915
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. NM-317230
7. Lease Name or Unit Agreement Name: V.M. Henderson
8. Well No. 9
9. Pool name or Wildcat Paddock Penrose Skelly GB, Tubb Oil

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/>	
2. Name of Operator Chevron Texaco Corporation	
3. Address of Operator P.O. Box 3109 Midland, Texas 79702	
4. Well Location Unit Letter <u>G</u> : <u>1,980</u> feet from the <u>North</u> line and <u>1,980</u> feet from the <u>East</u> line Section <u>30</u> Township <u>21S</u> Range <u>37E</u> NMPM Lea County	
10. Elevation (Show whether DR, RKB, RT, GR, etc.)	

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK <input type="checkbox"/> PLUG AND ABANDON <input type="checkbox"/> TEMPORARILY ABANDON <input type="checkbox"/> CHANGE PLANS <input type="checkbox"/> PULL OR ALTER CASING <input type="checkbox"/> MULTIPLE COMPLETION <input type="checkbox"/> OTHER: <input type="checkbox"/>	SUBSEQUENT REPORT OF: REMEDIAL WORK <input type="checkbox"/> ALTERING CASING <input type="checkbox"/> COMMENCE DRILLING OPNS. <input type="checkbox"/> PLUG AND ABANDONMENT <input checked="" type="checkbox"/> CASING TEST AND CEMENT JOB <input type="checkbox"/> OTHER: <input type="checkbox"/>

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach well bore diagram of proposed completion or recompletion.

- 1.) R/U on Y-Side, Tag CIBP @ 4,313 fill 2 3/8" casing w/25 sx plug 4,313' - 2,500' (Paddock) Tag @ 2,476 (Top pf fish @ 4,600')
- 2.) R/U on X-Side set 2 3/8" CIBP @ 3,850' (Penrose Kelly GB) fill 2 3/8" csg w/25 sx 3,550' - 2,500' Tag cmt @ 2,468'
- 3.) R/U on Z-Side set 2 3/8" CIBP @ 5,100' (Tubb Oil) Fill 2 3/8" csg w/45 sx 5,100' - 2,500' Tag cmt @ 2,465'
- 4.) Cut 3 csg strings @ 2,476', L/D csg spot 55 sx plug 2,476' - 2,300' (Stub) Tag cmt @ 2,256'
- 5.) Displace hole w/MLF 9.5# Brine w/25# gel P/BBL.
- 6.) Spot 55 sx plug 1,400' - 1,200' (T-Salt) Tag cmt @ 1,142'
- 7.) Spot 55 sx plug 400' - 200' (11 3/4" shoe) Tag cmt @ 285' ok w/OCD
- 8.) Circ cmt 30' to surf w/15'sx Install dry hole marker 11/27/01

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Jimmy Bagley TITLE MANAGER DATE 11/27/01

Type or print name Jimmy BAGLEY Telephone No. (915) 683-4996
(This space for State use)

APPROVED BY Compliance Officer TITLE COMPLIANCE OFFICER DATE 1 2002
Conditions of approval, if any:

GW